





# **Salem Central Public Library**

Submitted to City of Salem, Oregon

February 14, 2014

# **Evaluation Report**

City of Salem Salem Central Public Library

Submitted to

City of Salem Salem, Oregon

14 February 2014



Submitted by

BergerABAM 700 NE Multnomah Street, Suite 900 Portland, OR 97232

Job No. A14.0170.00

#### **EVALUATION REPORT**

#### City of Salem Salem Central Public Library

#### **TABLE OF CONTENTS**

## SECTION

#### PAGE

EXECU	TIVE SU	JMMAR	۲	iv
1.0	INTROI 1.1 1.2	DUCTIOI Genera Scope	N I	1 1 1
2.0	CONTE	NTS OF	REPORT	1
3.0	GEOTE	CHNICA	L AND SEISMIC DESIGN CRITERIA	2
	3.I 2.Q		al Colomia Coolom	2
	3.Z	Region	al Seismic Geology	2
	3.3	Level o	r Seismicity and Soli Type	4
	3.4	Seismi	c Performance Level	5
4.0	CITY O	F SALEN	I CENTRAL PUBLIC LIBRARY	5
	4.1	Library	Building	6
		4.1.1	General Building Description	6
		4.1.2	Building Type	7
		4.1.3	List of Assumptions	8
		4.1.4	Findings	8
		4.1.5	Recommendations	10
	4.2	Audito	rium Building	11
		4.2.1	General Description	12
		4.2.2	Building Type.	12
		4.2.3	List of Assumptions	12
		4.2.4	Findings	13
		4.2.5	Recommendations	14
	4.3	Parking	g Garage	14
		4.3.1	General Description	14
		4.3.2	Building Type.	15
		4.3.3	List of Assumptions	15
		4.3.4	Findings	15
		4.3.5	Recommendations	16
5.0	SEISM	IC UPGF	RADE OPINION OF PROBABLE CONSTRUCTION COST	17

#### APPENDICES

Appendix A - References Appendix B - Cost Estimate Appendix C - Proposed Renovation Drawings Appendix D - Site Photographs Appendix E - ASCE 31-03 Tier 1 Checklists

#### **EXECUTIVE SUMMARY**

This report documents a seismic structural and nonstructural assessment of City of Salem Central Library, which includes the main library building, the auditorium, and the adjacent parking garage. This report indicates descriptions, evaluations, and upgrade recommendations. The evaluations were performed in accordance with the checklists produced by the American Society of Civil Engineers (ASCE) in ASCE 31-03 *Seismic Evaluation of Existing Buildings*. This report is based on an ASCE 31-03 Tier 1 evaluation. Structural upgrades are based in part on the analysis procedures of ASCE 41-06 *Seismic Rehabilitation of Existing Buildings*. Before implementation of any seismic upgrade scheme, a complete ASCE 31-03 Tier 2 evaluation should be performed.

Three major components were considered in this seismic evaluation: the Library, the Auditorium, and the Parking Garage. While the Library and the Parking Garage require major seismic upgrades the Auditorium requires better out-of-plane attachments for the walls. The seismic upgrade for each component, along with the type of work involved, can be summarized as follows.

- Auditorium: estimated cost \$75,000
  - Reinforce anchorage of the roof to the concrete walls.
- Library: estimated cost \$5.224 million
  - Add new reinforced concrete shearwalls at four locations.
  - Add new micro-pile foundations to support the new concrete shearwalls.
  - Add collector elements at elevated levels in order to get seismic load to the new concrete shearwalls.
  - Reinforce the connections of elevated levels to existing concrete walls and piers.
  - Reinforce the connection of the composite metal deck to existing concrete waffle slabs and concrete walls.
  - Reinforce the connection of the metal roof deck to existing concrete waffle slabs and concrete walls.
  - Reinforce the connections of precast concrete spandrel beams to the structure.
- The Parking Garage: estimated cost \$1.098 million
  - Add new reinforced concrete shearwalls.

- Add collector elements at elevated levels in order to get seismic load to the new and existing concrete shearwalls.
- Reinforce the connections of precast concrete spandrel beams to the structure.

The costs listed above are direct construction costs only. See Appendix B, Direct Construction Cost Summary for a list of other cost categories to be included when considering the total project development cost.

Construction of these upgrades will likely disrupt the daily function of the facility and could make portions of each facility off-limits during construction.

# 1.0 INTRODUCTION

# 1.1 General

BergerABAM has been retained by the City of Salem to conduct building evaluations for the Salem Central Public Library campus. The facility includes three separate building structures: the Library building structure, the Auditorium building structure, and the adjacent Parking Garage structure. The purpose of this study is to evaluate the expected seismic performance of the existing buildings, and to determine the cost to rehabilitate the buildings to a life safety level of seismic performance.

Our evaluations of the existing buildings are based on visual observations, numerical calculations, and the review of the original design documents. Evaluation criteria from the ASCE 31-03 *Seismic Evaluation of Existing Buildings* and the ASCE 41-06 *Seismic Rehabilitation of Existing Buildings* were used, in part, as the basis of our structural assessment.

Observations, analyses, conclusions, and recommendations contained in this report reflect our best judgment. Concealed problems with the construction of the buildings may exist that were not revealed through this review. BergerABAM, therefore, is unable to warrant or guarantee the condition of the existing construction of the buildings.

# 1.2 Scope

The purpose of this study is to evaluate the expected seismic performance of the existing buildings, identify areas where structural and nonstructural improvements can or should be made, and evaluate their significance. Included in this work is estimated costs itemized for each structural element needed for the rehabilitation of the buildings.

Seismic condition assessments were conducted on all three existing building structures. The assessments were conducted in compliance with ASCE 31-03 Tier 1 standards. ASCE 41-06 *Seismic Rehabilitation of Existing Buildings* and a three-dimensional (3D) finite element computer program (ETABS<sup>®</sup>) were used to analyze the Library structure for proposed upgrades. Hand calculations were used to evaluate the Auditorium and the Parking Garage.

This report is intended to assist the City of Salem with determining the feasibility of rehabilitating the Salem Central Public Library building structures.

# 2.0 CONTENTS OF REPORT

This report presents the geotechnical and seismic design criteria and then describes each building in terms of its location, age, size, construction, and other general information. It also includes summaries of the buildings' structural and nonstructural systems, findings of the evaluation, and recommendations for changes to improve each building's seismic performance. The appendices include cost estimates, proposed renovation drawings, site photographs, and ASCE 31-03 Tier 1 checklists and supporting calculations.

Appendix E of the report contains the team's findings about the existing conditions of each building in terms of the criteria contained in five checklists found in ASCE 31-03 *Seismic Evaluation of Existing Buildings*: the Basic and Supplemental Structural Checklist, the Geologic Site Hazards and Foundations Checklist, and the Basic and Intermediate Nonstructural Component Checklists.

# 3.0 GEOTECHNICAL AND SEISMIC DESIGN CRITERIA

# 3.1 Geotechnical Data

At the time of this report, no geotechnical report was available. During the ASCE 31 analysis, no calculations were required that necessitated assumptions for the bearing capacity of the existing soil conditions. The existing drawings did list allowable soil bearing pressures used for the original design of the structure.

For the ASCE 31 evaluation to be complete, a licensed geotechnical engineer will be required to evaluate the site for the conditions listed in the Geologic Site Hazards and Foundations check lists that are located in Appendix E of this report. In particular, the potential geologic site hazards, such as liquefaction, surface fault rupture, and deterioration of foundation elements must be identified.

# 3.2 Regional Seismic Geology

There are three seismic source zones for earthquakes in the Pacific Northwest. These zones are illustrated in Figure 1 and include subduction zone interface, subduction zone intraplate, and crustal sources.



# Cascadia earthquake sources

#### Figure 1. Potential Seismic Source Zones for the Pacific Northwest (USGS, 2004)

The fault between the North American and the Juan de Fuca plate is the Cascadia Subduction Zone Interface and is a potential seismic source for the site. This source is at a depth of 6 to 12 miles and is located approximately beneath the coastline of western Oregon, Washington, and British Columbia. A typical subduction zone interface earthquake has a potential moment magnitude of 9.0. This type of earthquake's recurrence interval is approximately 500 to 600 years, based on historical and geologic information. The last known earthquake occurred in 1700 and indicates that the subduction zone is active.

Deep Cascadia Subduction Zone intraplate faults are also a potential seismic source. The Cascadia Subduction Zone intraplate source lies approximately directly beneath the site at a depth of 25 to 30 miles. Three earthquakes in recent history have been attributed to

this source. In 1949, 1965, and 2001 earthquakes with moment magnitudes of 7.1, 6.0, and 6.8, respectively, were observed. It is estimated that the intraplate source is capable of generating an earthquake with a maximum moment magnitude of 7.5 with an approximate return interval of 20 to 40 years.

Crustal sources are relatively shallow faults within the North American Plate and are generally considered within a certain distance from the site. This distance is commonly chosen as 60 miles. Crustal sources located more than 60 miles from the site are typically not capable of generating significant levels of shaking. There are numerous faults within 60 miles of the site, but there is much uncertainty in the classification of these sources, as only limited geological exploration has been conducted on most of the sources.

The historical seismicity for the region indicates that there have been five earthquakes with a magnitude greater than 5.0 since 1841. The largest recorded earthquake to affect the region was from the Cascadia Subduction Zone Interface. Other notable regional earthquakes were from crustal sources; the 1962 M5.5 Portland/Vancouver earthquake and the 1993 M5.6 Scotts Mill earthquake.

# 3.3 Level of Seismicity and Soil Type

To evaluate the buildings, ASCE 31-03 requires a classification of the site into one of three levels of seismicity: low, moderate, or high. These levels define a degree of expected earthquake hazard and are based on response acceleration values mapped by the United States Geological Survey (USGS). ASCE 31-03 uses a seismic recurrence period of a 2 percent chance of exceedance in 50 years, which is an average recurrence interval of 2,500 years.

A geotechnical evaluation was not performed as part of this evaluation. See Section 3.2 for information about regional seismic geology. ASCE 31-03 allows a soil Site Class D to be assumed in the absence of specific geotechnical information. Site Class D is defined as stiff soil with the following characteristics.

- 600 ft./sec. <  $v_s$  < 1,200 ft/sec, where  $v_s$  is the average shear wave velocity, or
- 15 < N < 50, where N is the average Standard Penetration Test blow count, or
- 1,000  $psf < s_u < 2,000 psf$ , where  $s_u$  is the average undrained shear strength of the upper 100 feet of soils at the site.

For determination of the site seismicity, a Site Class D was assumed. The response acceleration values are shown in Table 1 and were obtained from USGS data for the site based on latitude and longitude (USGS report may be found in Appendix E of this report). For the purpose of the Tier 1 evaluation of the three building structures, these values indicate that the building is located in a region of high seismicity.

Seismic Design Parameter	Value
Peak Ground Acceleration (PGA)	0.318
SDS (Design short period spectral response acceleration)	0.626
SD1 (Design spectral response acceleration at one-second period)	0.391

Table 1 - USGS Seismic Hazard Data for the Salem Library

# 3.4 Seismic Performance Level

The desired performance level for the City of Salem Central Library campus buildings is Life Safety, which is a level of building performance that includes damage to both structural and nonstructural components during a design earthquake, such that partial or total structural collapse does not occur, and the overall risk of life-threatening injury as a result of structural and nonstructural damage is expected to be low.

# 4.0 CITY OF SALEM CENTRAL PUBLIC LIBRARY

The City of Salem's Central Public Library is located at 585 Liberty Street SE in Salem, Oregon, and shares a campus with Salem City Hall. The original library building was constructed in 1970 and currently serves Salem's 135,000 residents 53 hours a week. The Library campus is located on a sloped landscape. Modifications were made to the building in 1990 to add 38,100 square feet to the Library



City of Salem Central Public Library

structure. Also in 1990, a 5,020-square-foot Auditorium and a 90,384-square-foot multistory Parking Garage were constructed.

A series of building improvements occurred between 1996 and 2010; however, it does not appear the building structure was altered.

The original design and construction documents provided for the library are dated March 1970 and the expansion project documents are dated November 1989. Both sets of plans included architectural and structural drawings showing site plans, floor plans, building elevations, sections, details, and schedules. The existing drawings provided were reviewed and compared for consistency with the as-built construction by performing a site visit of the facility.

On 26 November 2013, two BergerABAM engineers performed a walkthrough of the facility to verify as-built conditions and to perform a site visit consistent with requirements for the preparation of an ASCE 31, Tier 1 Seismic Evaluation. While on site, BergerABAM personnel met with the City of Salem Engineering Program Manager, Mr. Allen Dannen, PE, to discuss existing building functions and known renovations or alterations that would be useful information for preparation of the seismic evaluation report. The site visit covered the Library (lower floor, main floor, second floor and roof), the Auditorium, and the Parking Garage. The perimeters of all three buildings were observed. During the site visit, field notes were recorded to include observations of any structural seismic deficiencies and a photographic inventory of over 500 photographs was collected.

# 4.1 Library Building

# 4.1.1 General Building Description

The Library is a three-story building approximately 38 feet tall from the ground to top of the roof parapet on the north side of the building. The grade slopes from an elevation of 177 feet on the north side of the building to an elevation of 189 feet(+) on the south side of the building. The lower floor is at an elevation of 177 feet, the main floor is at an elevation of 189 feet, the second floor is at an elevation of 201 feet 6 inches and the roof varies between 213 feet 6 inches to 214 feet 10 inches. The total area of the original structure is 52,278 square feet, which includes a 21,576-square-foot lower level, a 21,576-square-foot main level, and a 9,576-square-foot second level. During the 1990 expansion, a total of 38,100 square feet was added to the building. This upgrade added 10, 850 square feet to both the lower floor and main floor and 16,720 square feet to the second floor. The total area of the Library today is approximately 91,148 square feet, which includes a 32,426-square-foot lower level, a 38,296-square-foot main floor, and a 20,426-square-foot second floor.

# 4.1.1.1 Structural System Description

The original library building constructed in 1970 sits on shallow spread footings. Typically, the lower level slab is 5 inches thick and on grade. Framing for all other levels consists of a 14-inch deep, cast-in-place reinforced concrete waffle slab with reinforced concrete columns and walls. The lateral-force-resisting system includes the original exterior 20-inch by 7-foot concrete piers in addition to the 8-inch and 10-inch-thick reinforced concrete walls of both the elevator shaft and the south stair well. For the lower floor only, the 12-inch-thick retaining walls act as lateral-force-resisting elements. The retaining walls are located on the east, west and south sides of the building. The north side of the lower floor daylights to a plaza. The roof is composed of built-up roofing and gravel over a 14-inch cast-in-place reinforced concrete waffle slab. According to original construction documents, all columns and walls are doweled into shallow spread footings.

The 1990 expansion also sits on shallow spread footings. The framing consists of steel columns and beams, 3-1/2-inch normal weight concrete over 2-inch formed-steel metal decking, and reinforced concrete walls. The columns are attached to the spread footings via four 1-inch-diameter anchor bolts. Reinforced 12-inch concrete retaining walls are doweled into shallow spread footings. The lower floor is composed of a 5-inch thick concrete slab on grade. The roof structure is composed of 1 1/2-inch metal decking over steel beams. No additional lateral force resisting elements were constructed in 1990. To resist lateral forces, the 1990 expansion relies on the 8-inch, 10-inch and 12-inch reinforced concrete exterior walls, the 8-inch and 10-inch-thick walls of the south stairwell, and the 20-inch by 7-foot exterior columns of the original building.

# 4.1.1.2 Nonstructural Systems Description

The exterior of the original building constructed in 1970 consists of reinforced concrete walls, precast sills, and glazing. To the best of our knowledge, the glazing is neither laminated annealed nor laminated heat-strengthened safety glass. Furthermore, the glazing attachment to concrete does not allow for relative displacement. Precast concrete fascia is used along the entire exterior of the roofline. The acoustical ceilings are dropped and suspended from the waffle slab system.

The exterior of the 1990 expansion area of the main building consists of reinforced concrete walls, precast spandrels, and glazing. To the best of our knowledge, the glazing is neither laminated annealed nor laminated heat-strengthened safety glass. There is a large circular skylight in the 1990 expansion area of the south side of the building that creates a light-well through the second floor.

Large book stacks, shelving units, and storage racks over 4 feet 6 inches in height can be found throughout the building. The building also contains a coffee shop with miscellaneous equipment on the lower level. There are several refrigerators, vending machines, wall-mounted televisions, and display cabinets found throughout the building.

Photographs of the interiors and the exteriors of the building are included in Appendix D.

# 4.1.2 Building Type

By ASCE 31 definitions, the main building was evaluated as a C2-type building: Concrete Shear Walls with Stiff Diaphragms. The floor and roof framing of this building type consists of cast-in-place concrete slabs, concrete beams, one-way joists, two-way waffle joists, or flat slabs. Floors are supported on concrete columns or bearing walls. Lateral forces are resisted by cast-in-place concrete shear walls. In older construction, shear walls are lightly reinforced but often extend throughout the building. In more recent construction, shear walls occur in isolated locations and are more heavily reinforced with boundary elements and closely spaced ties to provide ductile performance. The diaphragms consist of concrete slabs and are stiff relative to the walls. Foundations consist of concrete spread footings, mat foundations, or deep foundations.

# 4.1.3 List of Assumptions

The following assumptions were made regarding the seismic performance of the Library building. The assumptions are made because of a lack of information provided by structural documentation and to outline standard practice of evaluating lateral force-resisting systems.

- Concrete strength is f'c = 4,000 psi and 3,000 psi, depending on the component.
- Normal weight reinforced concrete weighs 150 pcf
- Rebar strength fy = 60ksi

# 4.1.4 Findings

The library building has been evaluated for a Life Safety performance objective for the Design Earthquake as defined in ASCE 31-03 *Seismic Evaluation of Existing Buildings*. Based on the procedures of ASCE 31, the following deficiencies in the building's lateral-force-resisting system and nonstructural components were identified.

# 4.1.4.1 General Basic and Supplemental Structural Checklists (3.7.9 and 3.7.9S):

- A Weak Story occurs at the second floor because there is a significant reduction in the number of lateral load resisting elements and the capacity of those elements, from the main level to the second level directly above.
- A Soft Story occurs at the second floor because the stiffness of the lateral-forceresisting system of the main level is 70 percent more than the stiffness of the second story. Because of large openings and irregularities, the diaphragm is unable to redistribute seismic inertial forces to shearwalls throughout the building.
- At the main floor, the estimated distance between the story center of mass and the story center of rigidity is approximately 35 feet, and twenty percent of the building width in the north-south direction is approximately 33 feet. Thus, the building may have inherent torsional issues.
- For loading in the east-west direction and using the ASCE 31 Tier 1 evaluation procedure, the shear stress in the concrete shear walls on the second floor exceeds allowable limits.
- Based on the original construction drawings, the ratio of the horizontal reinforcing steel area to gross area of concrete for the shear walls is less than the recommended 0.0025.
- The 24-inch by 24-inch reinforced columns spanning from top to bottom of the building structure have insufficient shear reinforcement to develop the maximum

probable moment capacity (Mpr). The computed capacity of the existing (E) column is only 54 percent of the maximum shear demand of 92 kips.

# 4.1.4.2 Basic and Intermediate Non-Structural Component Checklists (3.9.1 and 3.9.2):

Inadequately attached non-structural elements can cause significant damage in the building, resulting in very expensive repairs and rendering it inoperable for an extended period of time after the earthquake. In addition, falling contents are often harmful to the building occupants during an earthquake, with the young and elderly being particularly vulnerable to casualty and sometimes fatality.

- The stairs do not appear to have slip connections to accommodate differential story drift. This may cause an unintended load path for seismic demands.
- The precast concrete fascia panels on the exterior of the roof of the original building are anchored at 7 feet 6 inches on center. The precast concrete fascia panels on the exterior of the 1990 expansion part of the building are anchored where the steel framing meets the concrete panels at roughly 8 feet on center. It is unclear from the plans how the relocated window/wall system on the north side of the building is attached to the main structure. Further investigation would be required to verify adequate anchorage.
- Tall contents in the building consist of unbraced book stacks, shelving units, file cabinets, lockers, and other miscellaneous furniture with a height-to-width or a height-to-depth ratio greater than 3-to-1 on all levels of the Library. These can pose a toppling hazard during an earthquake.
- There appears to be inadequate lateral bracing of the fire suppression system, including both sprinkler heads and piping, along with areas where the impact of sprinkler pipes with other unbraced nonstructural elements could result in unreliable performance. Inadequately braced fire sprinkler piping has performed poorly in past earthquakes, rendering systems unusable when most needed.
- Gas piping throughout the building does not appear to have flexible couplings, which could lead to a pipe fracture in an earthquake. This can cause a fire hazard during a seismic event, often causing more damage to the building and its contents than from structural damage alone.
- Anchorage supports on many of the pumps in the mechanical room show signs of corrosion. There is also surface corrosion on steel pipes in the mechanical room area of the building.
- The hot water heater in the mechanical room is not braced for lateral support.
- Piping from the hot water heater to the floor above does not have flexible couplings.

- There appears to be no lateral bracing of the integrated suspended ceiling system in many areas throughout the Library.
- The light fixtures in the suspended grid ceiling are not supported independently of the ceiling suspension system.
- There are several pieces of equipment weighing over 20 pounds attached to ceilings or walls that are not laterally braced.
- Glass from original building does not appear to be safety glass except in panes over five feet in dimension. Safety glass is required at egress areas. In addition, the connection of glass to structure does not allow for the differential displacements expected.

# 4.1.5 Recommendations

Because of the deficiencies described above, the library building does not meet the Life Safety performance objective of an ASCE 31 Tier 1 seismic evaluation. To achieve a Life Safety performance level for this building, the following strengthening scheme is proposed. Before any structural upgrades are performed, a complete Tier 2 seismic evaluation of the structure is required. See the Proposed Renovation Drawings in Appendix E.

# 4.1.5.1 Structural

- Provide new concrete shearwalls from the ground to the roof level.
- Provide new concrete foundations with micro-piles to support the new concrete shearwalls and allow them to resist the lateral seismic loads.
- Provide new collector elements throughout the elevated floors and roof to help distribute the seismic demands to the new concrete shearwalls.
- Improve connectivity of the existing concrete slabs to the existing concrete walls and piers.
- Reinforce the connections of the existing steel beams to the existing concrete piers at the second level.
- Strengthen the connectivity of the existing composite metal deck and metal roof deck to the existing concrete slabs and walls.
- Reinforce the concrete diaphragm around the stair opening in the slab on the second level.

#### 4.1.5.2 Nonstructural

- Provide slip connections in stairs spanning between floors to prevent damage during the design-level earthquake.
- Further analysis should be conducted on the precast concrete panels along the exterior of the roof level to ensure that the anchorage scheme meets current seismic code. If it is determined that the anchors are insufficient, additional anchors should be installed to ensure that panels do not break free from building during the design-level earthquake.
- Tall narrow contents in the building, including book stacks, storage shelving, and equipment over 4 feet in height and with a height-to-depth or height-to-width ratio greater than 3-to-1, should be anchored to the floor slab or adjacent structural walls. Existing book stacks do not appear to have brackets to allow anchorage to the structure. The existing stacks will require a retrofit or new book stacks with anchor points will be needed.
- Provide lateral bracing and flexible couplings for all fluid, gas, and fire suppression piping.
- Brace fire suppression piping per NFPA-13.
- Remove corrosion on nonstructural elements. Protect nonstructural elements from future corrosion.
- The hot water heater in the mechanical room should be braced to the wall or anchored to the floor.
- The ladder in the mechanical room should be braced, anchored to the floor, or stored somewhere where it does not present a potential falling hazard while not in use.
- Provide lateral bracing for the suspended ceiling system throughout the entire building.
- Provide lateral bracing for the light fixtures in the suspended ceiling system independent of the ceiling system bracing.
- Brace equipment weighing over 20 pounds that is attached to ceilings, walls, or other supports four feet above the floor level.
- Provide safety glass where required. Replace window systems to allow for differential displacements.

# 4.2 Auditorium Building

## 4.2.1 General Description

The Auditorium was constructed in 1990 as part of the City of Salem Central Library Expansion project. The total area of the circular structure is 5,020 square feet. Typical exterior walls are 8-inch-thick cast-in-place reinforced concrete. The main level is on grade and the roof is at a maximum height of 20 feet above grade. The interior of the Auditorium is open, with very few partition walls.

## 4.2.1.1 Structural System Description

The 8-inch-thick exterior walls make up the lateral-force-resisting system of this building. The roof framing consists of 1 1/2-inch metal deck over steel open web joist and steel beams. The non-composite metal deck roof system is flexible compared to the walls. There are four tube steel columns supporting the roof system. The main floor is slab on grade. The structural elements sit on shallow foundations and, according to original construction documents, all columns and walls are doweled into the spread footings.

The northwest portion of the Auditorium is attached to the Library. The Auditorium structural wall sits over the top of a 12-inch subgrade wall. This concrete wall supports a small area of the Library roof that is located above the second floor level and below the main roof. The Auditorium roof structure consists of 1 1/2-inch metal roof deck over steel open-web joists and steel beams.

#### 4.2.1.2 Nonstructural Systems Description

There is no cladding or veneer on the structure. The interior ceiling has many pieces of suspended equipment along with acoustical panels. There is a suspended projection screen over the main stage area. The interior walls are gypsum board over metal studs. The HVAC ducting is suspended from the roof joists.

# 4.2.2 Building Type

The Auditorium was evaluated as a Type C2A building: Concrete Shear Walls with Flexible Diaphragms. These buildings are similar to C2 buildings, except that the diaphragms consist of wood sheathing on wood framing or metal deck on steel framing, Lateral forces are resisted by cast-in-place concrete shear walls. In general, shear walls in older construction are lightly reinforced but often extend throughout the building. For more recent construction however, shear walls occur in isolated locations, are more heavily reinforced with boundary elements and closely spaced ties to provide ductile performance. The diaphragms consist of wood sheathing or metal deck, have large aspect ratios and are flexible relative to the walls. Foundations consist of concrete spread footings or deep foundations.

#### 4.2.3 List of Assumptions

The following assumptions were made regarding the seismic performance of the Auditorium. The assumptions are made because of a lack of information provided by structural documentation and to outline standard practice of evaluating lateral-force-resisting systems.

- The Library structure and the Auditorium are not seismically connected and act as separate structural systems.
- Interior partition walls do not contribute to the lateral-force-resisting system.
- Structural walls consist of the following.
  - Concrete strength of f'c = 3,000 psi
  - Normal-weight concrete weighing 150 pcf
  - Reinforcing steel strength of fy = 60 ksi

# 4.2.4 Findings

The Auditorium has been evaluated for a Life Safety performance objective for the design earthquake as defined in ASCE 31-03 *Seismic Evaluation of Existing Buildings*. Based on the procedures of ASCE 31, the following deficiencies in the building's lateral force resisting system and non-structural components were identified.

# 4.2.4.1 General Basic and Supplemental Structural Checklists (3.7.16 and 3.7.16S)

- The Library building and the Auditorium from the 1990 expansion project do not have adequate seismic joints and could result in building pounding during an earthquake. Building pounding can result in highly adverse seismic behavior in one or both building components.
- To prevent pounding, the needed clear distance is 10 inches, which is equivalent to a setback of two percent of the potential contact height of each building.
- Based on the original construction drawings, the ratio of the horizontal reinforcing steel area to gross area of concrete is less than the recommended 0.0025 for the 8-inch-thick reinforced concrete shearwalls.
- The roof diaphragm is inadequately attached to the exterior walls. The original construction drawings show the roof deck attaches to the exterior 8-inch concrete walls with a single 5/8-inch diameter by 5-inch wedge anchor at 48 inches on center. These anchors are no longer deemed appropriate for use in seismic conditions because of their unreliable performance. However, to evaluate the demand-to-capacity ratio of this attachment, anchor capacity was computed using a comparable 5/8-inch diameter, Hilti Kwik-Bolt II anchor with a 4-inch embedment depth. The computed demand is nearly 1.5 times the capacity of the anchor as computed according to the approved seismic performance report (ER-4627).
- The stirrups in the coupling beams, overhead of the primary means of egress for the Auditorium, are hooked with 90-degree bends according to the original construction drawings. Current practice for the design of concrete coupling beams includes hooks of 135 degrees or more to develop reinforcing steel.

#### 4.2.4.2 Basic, Intermediate and Supplemental Nonstructural Component Checklists (3.9.1, 3.9.2 and 3.9.3)

- There appears to be no lateral bracing for the suspended equipment or the suspended acoustical panels in the auditorium.
- The suspended light fixtures in the auditorium appear to not be laterally braced.
- The fire-suppression piping does not appear to have lateral bracing.

# 4.2.5 Recommendations

Because of the deficiencies described above, the Auditorium does not meet the Life Safety performance objective of ASCE 31. To achieve a Life Safety performance level, the following strengthening scheme is proposed. Before any structural upgrades are performed, a complete Tier 2 seismic evaluation of the structure is required.

#### 4.2.5.1 Structural

• Reinforce the anchorage of the roof to the concrete walls.

# 4.2.5.2 Nonstructural

- Brace equipment weighing over 20 lbs that is attached to ceilings, walls, or other supports four feet above the floor level.
- Brace fire suppression piping per NFPA-13.

# 4.3 Parking Garage

# 4.3.1 General Description

The Parking Garage was constructed in 1990 as part of the City of Salem Central Library Expansion project. The total area of the structure is 90,384 square feet. The lower level is a sloping slab on grade, the middle level is sloping at 10.67 feet above the lower level and the upper level is sloping at 10.67 feet above the middle level to a maximum height of 32 feet above grade. The garage is an open design and as such does not have any mechanical exhaust systems.

# 4.3.1.1 Structural System Description

The Parking Garage sits on a shallow spread footing foundation. The garage has a 6-inch concrete slab on grade with #4 reinforcing steel at 12-inches on center each way, supported by a compacted gravel base. The elevated floor framing of the Parking Garage consists of 28-inch-deep pre-cast double-tee joists, which are supported by corbels at columns, beams and walls. The exterior gravity supports are 18-inch by 18-inch columns typically spaced at 24 feet on center The double-tees have a 3-inch topping slab with #4 reinforcing steel at 12-inches on center each way that is doweled into spandrels beams, walls, and vertical concrete columns. The lateral force resisting system consists of reinforced concrete shearwalls: 10-inch-thick concrete walls are along the exterior of the building and a 12-inch-thick full height concrete shearwall runs down the center of the

building. According to original construction documents, all columns and walls are doweled into shallow spread footings.

## 4.3.1.2 Nonstructural Systems Description

The exterior cladding of the building is precast concrete panels.

## 4.3.2 Building Type

By ASCE 31 definitions, the parking garage was evaluated as a C2-type building: Concrete Shear Walls with Stiff Diaphragms. The floor and roof framing of this building type consists of cast-in-place concrete slabs, concrete beams, one-way joists, two-way waffle joists, or flat slabs. Floors are supported on concrete columns or bearing walls. Lateral forces are resisted by cast-in-place concrete shear walls. In older construction, shear walls are lightly reinforced but often extend throughout the building. In more recent construction, shear walls occur in isolated locations, are more heavily reinforced with boundary elements and closely spaced ties to provide ductile performance. The diaphragms consist of concrete slabs, and are stiff relative to the walls. Foundations consist of concrete spread footings, mat foundations, or deep foundations.

# 4.3.3 List of Assumptions

The following assumptions were made regarding the seismic performance of the Parking Garage. The assumptions are made because of a lack of information provided by structural documentation and to outline standard practice of evaluating lateral force resisting systems.

- Concrete strength of f'c = 3,000 psi.
- Normal-weight concrete weighing 150 pcf.
- Reinforcing steel strength of fy = 60ksi.

# 4.3.4 Findings

The Parking Garage has been evaluated for a Life Safety performance objective for the design earthquake as defined in ASCE 31-03 *Seismic Evaluation of Existing Buildings*. Based on the procedures of ASCE 31, the following deficiencies in the building's lateral-force-resisting system and nonstructural components were identified.

# 4.3.4.1 General Basic and Supplemental Structural Checklists (3.7.16 and 3.7.16S)

- The garage does not pass the Weak Story evaluation. The strength of the lateral force-resisting system supporting the upper level is 49 percent less than the lateral-force resisting system of the middle level.
- A Soft Story occurs between the upper level and the middle level of the garage. In both the north-south and the east-west directions, the upper story has less than 70 percent of the lateral-force-resisting system stiffness of the middle story.
- The distance between the story center of mass and the story center of rigidity is greater than the recommended 20 percent. There could be substantial rotation of the

diaphragm that could lead to increased demands in the columns that were not designed to be part of the lateral-force-resisting system.

- There is some minor cracking of the concrete on all areas of the building and around a few connections of the precast panels. The concrete is also deteriorating around some of the double-tee joist connections to exterior beams.
- Collector elements are not provided at reentrant corners of the diaphragm.
- The shear stress in the concrete shear walls, calculated using the Quick Check procedure, exceeds the permissible limit for all levels of the parking garage in the N-S direction of loading. The demand-to-capacity ratios range from 1.1 to 3.5. Demand-to-capacity ratios in excess of 1.0 are considered deficient.
- Secondary components do not have the shear capacity to develop their flexural strength. The 18- by 18-inch reinforced columns do not have enough shear reinforcement to develop the maximum probable moment, Mpr, or the capacity most likely achieved by the element. The shear demand is roughly twice the existing capacity.

#### 4.3.4.2 Basic, Intermediate and Supplemental Non-Structural Component Checklists (3.9.1, 3.9.2 and 3.9.3)

- Cladding components weighing more than 10 psfshall be anchored at a spacing equal to or less than four feet. The precast concrete panels used on the exterior of the parking garage weigh more than 10 psf and are anchored at each end, or at an approximate 24-foot spacing.
- Corrosion was observed on many connecting elements, and a few connections appeared to be damaged or compromised.
- The connections of the precast concrete panel cladding to exterior columns do not have slotted connections, and therefore do not accommodate a story drift ratio of two percent.
- There are some exterior cladding panels that have fewer than four connections for each wall panel.

# 4.3.5 Recommendations

Because of the deficiencies described above, the parking garage does not meet the Life Safety performance objective of ASCE 31. To achieve a Life Safety performance level, the following strengthening scheme is proposed. Before any structural upgrades are performed, a complete Tier 2 seismic evaluation of the structure is required. See the Proposed Renovation Drawings in Appendix C.

# 4.3.5.1 Structural

Add new reinforced concrete shearwalls.

- Add collector elements at elevated levels in order to get seismic load to the new and existing concrete shearwalls.
- Reinforce the connections of precast concrete spandrel beams to the structure.

# 4.3.5.2 Non-structural

Further analysis should be conducted on the precast concrete panels along the exterior of the structure to ensure that the anchorage scheme meets current seismic code. If it is determined that the anchors are insufficient, additional anchors should be installed to ensure that panels do not break loose from the building during a design earthquake event.

Provide slip connections in anchoring brackets for the precast panel cladding.

# 5.0 SEISMIC UPGRADE OPINION OF PROBABLE CONSTRUCTION COST

The estimated probable construction cost for the proposed upgrades are summarized as follows:

Component	Area	\$/SF	Total
Library Main Building	91,148 sf	57.31	\$5,224,000
Auditorium Building	5,020 sf	14.94	\$75,000
Parking Garage	90,384 sf	12.15	\$1,098,000

 Table 2 - Opinion of Probable Construction Cost

See Appendix B for a detailed cost analysis and important assumptions and exclusions related to this estimate.

Evaluation Report Salem Central Public Library City of Salem, Salem, Oregon

> Appendix A References

#### REFERENCES

- ASCE 31-03, Seismic Evaluation of Existing Buildings. American Society of Civil Engineers. 2003
- ASCE 41-06, *Seismic Rehabilitation of Existing Buildings*. American Society of Civil Engineers. 2006
- ACI 318-08, Building Code Requirements for Structural Concrete and Commentary. American Concrete Institute. 2008
- ASCE 7-05, *Minimum Design Loads for Buildings and Other Structures*. American Society of Civil Engineers. 2006

Evaluation Report Salem Central Public Library City of Salem, Salem, Oregon

> Appendix B Cost Estimate

#### Salem Central Public Library

Seismic Upgrade Evaluation Report City of Salem, Oregon BergerABAM Evaluation Report Probable Cost Estimate - 1.2 Architectural Cost Consultants, LLC

Stanley J. Pszczolkowski, AIA 8060 SW Pfaffle Street, Suite 110 Tigard, Oregon 97223-8489 Phone (503) 718-0075 Fax (503) 718-0077 www.archcost.com

# DIRECT CONSTRUCTION COST SUMMARY

Component	Area		\$ / SF	Total
01   Library Main Building	91.148	sf	57.31	\$5,224,000
02   Auditorium Building	5,020	sf	14.94	\$75,000
03   Parking Garage	90,384	sf	12.15	\$1,098,000

The above estimates are for direct construction cost only. They do not include furnishings & equipment, architect and engineer design fees, consultant fees, inspection and testing fees, plan check fees, state sales tax, hazardous material testing and removal, financing costs, owners contingency nor any other normally associated project and development costs.

The above estimates assume a competitively bid project, with at least three qualified bidders in each of the major sub-trades as well as the general contractors.

The above estimates assume a construction start date of: Winter 2016. If the start of construction is delayed beyond the date above, the estimates must be indexed at a rate of 3 to 4% per year compounded.

This is a probable cost estimate based on in-progress documentation provided by the architect. The actual bid documents will vary from this estimate due to document completion, detailing, specification, addendum, etc.. The estimator has no control over the cost or availability of labor, equipment, materials, over market conditions or contractor's method of pricing, contractor's construction logistics and scheduling. This estimate is formulated on the estimators professional judgment and experience. The estimate makes no warranty, expressed or implied, that the quantities, bids or the negotiated cost of the work will not vary from the estimators opinion of probable construction cost.

The above costs are rounded to the nearest 1,000.

The estimate makes an attempt to identify other systems scope of work to support the structural seismic work. A formal study is recommended to evaluate impacts to architectural, electrical and mechanical systems. Impacts to code requirements, existing pathways, etc.. Cost identified may not necessarily or adequately cover the required work to support this structural scope of work.

Salem Central Public Library	AI	chitect	Estimate Date: R27- Jab-14				
Seismic Upgrade Evaluation Report		S	Document Date: 20-Dec-13				
City of Salem, Oregon		806	Print Date: 27-Jan-14				
BergerABAM		٦	Figard, Oregon 9	Print Time: 1:16 PM			
Evaluation Report Probable Cost Estimate - 1.2	Phone (5	03) 718-0	075 Fax (503)	rchcost.com	Constr. Start: Winter 2016		
Alternates	Quantity	Unit	Cost / Unit		Cost	Sub-totals	Comments
01   Library Main Building							
Demolition			• • • • • •		•		
sawcut slab on grade	256	lf	\$10.00		\$2,560		
remove slab on grade	768	sf	5.00		3,840		
remove windows	10,000	st	6.00		60,000		
temp shore / barricades / protect / cleanup	91,148	ST	2.00		182,296		allowance
misc. support / cut / patch	16	sum	3,500.00		56,000		allowance
naul & disposal	1	sum	16,600.00	1-6	16,600	¢224.206	-
Sub-iolai	91,148	SI	3.52	/SI		<i>ф321,290</i>	
Earthwork							
excavate for footing, neat cut	90	су	\$150.00		\$13,500		by hand
haul & disposal	90	су	50.00		4,500		_
Sub-total	91,148	sf	0.20	/sf		\$18,000	
Piling							
mobilization / building access	1	sum	\$10.000.00		\$10.000		
100 ton micro piles	88	ea	4.000.00		352.000		premium for in bldg, work
Sub-total	91,148	sf	3.97	/sf	,	\$362,000	
Concerts work							
Concrete work							
footings		of	¢0.00		¢O		NIC assume earth form
welle	6.012	5i of	\$0.00 12.50		φ0 96 400		NIC - assume earth form
walls r/s	0,912	51	12.50		00,400		
footings	11 750	lhs	0.95		11 163		
walls	39 250	lbs	0.95		37 288		
drill / dowel / core	00,200	100	0.00		07,200		
dowel @ sog	192	ea	25.00		4.800		
dowel to exist footings	8	lctns	2.000.00		16.000		
core elevated slab for shear wall steel	8	lctns	5.000.00		40.000		allowance
dowel shear wall to roof slab	4	lctns	2.000.00		8.000		allowance
redi-mix			,		- ,		
4000 psi	251	су	105.00		26,355		
place							
footings	94	су	25.00		2,350		
walls	157	су	105.00		16,485		
pump / transport concrete	251	су	75.00		18,825		
finish							
footing / slab finish	768	sf	1.00		768		
wall - break ties / patch	6,912	sf	2.25		15,552		
misc.	1	sum	25,000.00		25,000		-
Sub-total	91,148	sf	3.39	/sf		\$308,986	
Steel							
new collector elements	1,345	lf	125.00		168,125		bolt to underside of waffle slab
rigging	1	sum	30,000.00		30,000		
reinforce connection conc. piers to slab	44	ea	850.00		37,400		
reinforce cnnctn composite deck to wall	64	lf	100.00		6,400		main floor, verify qty
reinforce cnnctn stl beam to conc. clmn	12	ea	750.00		9,000		2nd flr
reinforce cnnctn composite deck to waffle	167	lf	100.00		16,700		2nd flr
reinforce diaphragm @ opening	128	lf	100.00		12,800		2nd flr
reinforce precast cladding cnnctns	214	lf	75.00		16,050		2nd flr, verify qty
reinforce precast beam spandrel attach.	555	lf	100.00		55,500		roof, verify qty
reinforce precast cladding cnnctns	214	lt	85.00		18,190	<b>007</b> 0 407	roof, verify qty
Sud-total	91,148	st	4.06	/sf		\$370,165	l

Salem Central Public Library	Ar	chitecti	Estimate Date: R27-Jab-			
Seismic Upgrade Evaluation Report		St	Document Date:20-Dec-1Print Date:27-Jan-1Print Time:1:16 P			
City of Salem, Oregon		8060				
BergerABAM		Т				
Evaluation Report Probable Cost Estimate - 1.2	Phone (5	03) 718-00	archcost.com	Constr. Start: Winter 20		
Alternates	Quantity	Unit	Cost / Unit	Cost	Sub-totals	Comments
01   Library Main Building - Continued						
Architectural Finishes						
romovo / ropair to support structural	01 1 / 9	of	10.00	011 490		
	91,140	5i of	2.50	76 125		allowance
now windows	10,000	5i of	Z.30	F80 000		allowance
Sub-total	91,148	sf	17.20 J	/sf	\$1,567,605	-
Mechanical / Electrical	01 1 4 9	of	F 00	455 740		
remove / repair to support structural	91,148	SI	5.00	455,740	¢ 455 740	allowance
Sub-total	91,148	st	5.00	/sf	\$455,740	
Non-structural - Allowances		<i>.</i>		<b>A</b>		A feasibility study is
slip connections @ stairs	6	flght	10,000.00	\$60,000		recommended to evaluate
connections in anchoring precast panels	860	lf	85.00	73,100		/ investigate actual rqrmnts.
anchor tall narrow contents	91,148	sf	0.00	0		NIC - shelving not bracable
lateral bracing and flexible couplings	91,148	sf	0.15	13,672		
ductwork bracing	91,148	sf	0.20	18,230		
pipework bracing	91,148	sf	0.75	68,361		
hvac equipment	91,148	sf	0.35	31,902		
remove corrosion on nonstructural elements	91,148	sf	0.20	18,230		
ceiling lateral bracing	91,148	sf	0.15	13,672		
light fixture bracing	91,148	sf	0.15	13,672		
misc. clg patch / repair for above work	91,148	sf	0.30	27,344		
Sub-total	91,148	sf	3.71	/sf	\$338,183	
SUB-TOTAL 01   Library Main Building				3,741,975	\$3,741,975	
Estimating Contingency			15 00%	561 206		
Index To Construction Start	Winter 2016		7 1 2 %	306 303		@ 1.4% por voor
General Conditions / Insurance / Bond	winter 2016		0.50%	300,393 437 018		e ± 4% per year
General Contractor OH & Profit			9.50% 3.50%	176,665	1,482,273	per BergerAbam 39.61%
					, ,	
TOTAL DIRECT CONSTRUCTION COST	01 1 4 9	cf	¢57.20	lef.	¢5 224 249	
	91,140	51	\$31.3Z	/51	<b>\$</b> 3,224,240	
02   Auditorium Building						
Seismic Work						
reinforce precast cladding cnnctns	240	lf	75.00	18,000		roof, verify qty
arch. finishes patch / repair	240	lf	35.00	8,400		allowance
remove & replace windows	200	sf	64.90	12,980		
Sub-total	5,020	sf	7.84	/sf	\$39,380	
Non-structural - Allowances						
lateral bracing and flexible couplings	5.020	sf	0.20	1.004		
ductwork bracing	5.020	sf	0.30	1.506		
pipework bracing	5.020	sf	0.85	4.267		
hvac equipment	5.020	sf	0.45	2.259		
remove corrosion on nonstructural element	5.020	sf	0.25	1.255		
ceiling lateral bracing	5.020	sf	0.20	1.004		
light fixture bracing	5.020	sf	0.20	1.004		
misc, clg patch / repair for above work	5.020	sf	0.45	2 259		
	5,020	<u>,</u>	0.40	2,200	¢44 550	1
Sub-total	5 020	SI	2 qn .	/SI	314 222	

Salem Central Public Library	Ar	chitect	Estimate Date:	R27-Jab-14			
Seismic Upgrade Evaluation Report		S	tanley J. Pszczolkow	/ski, AIA		Document Date:	20-Dec-13
City of Salem, Oregon		806	0 SW Pfaffle Street,	Suite 110		Print Date:	27-Jan-14
BergerABAM		٦	Figard, Oregon 9722	3-8489		Print Time:	1:16 PM
Evaluation Report Probable Cost Estimate - 1.2	Phone (50	03) 718-0	075 Fax (503) 718	-0077 www.a	rchcost.com	Constr. Start:	Winter 2016
Alternates	Quantity	Unit	Cost / Unit	Cost	Sub-totals	Comme	ents
SUB-TOTAL 02   Auditorium Building				53,938	\$53,938		
Estimating Contingency Index To Construction Start General Conditions / Insurance / Bond General Contractor OH & Profit	Winter 2016		15.00% 7.12% 9.50% 3.50%	8,091 4,416 6,312 2,547	21,366	@ ± 4% per year per BergerAbam per BergerAbam	39.61%
TOTAL DIRECT CONSTRUCTION COST 02   Auditorium Building	5,020	sf	\$15.00 /s	f	\$75,304		

Salem Central Public Library	A	rchitect	Estimate Date: R27-Jab-1			
Seismic Upgrade Evaluation Report		St	Document Date: 20-Dec-13			
City of Salem. Oregon		806	Print Date: 27-Jan-14 Print Time: 1:16 PM			
BergerABAM		T				
Evaluation Report Probable Cost Estimate - 1.2	Phone (5	503) 718-00	Constr. Start: Winter 2016			
Alternates	Quantity	Únit	Cost / Unit	Cost	Sub-totals	Comments
02   Darking Carago						
03   Parking Garage						
Demolition	004		<b>#0</b> 00	<b>.</b>		
sawcut slab on grade	264	IT	\$6.00	\$1,584	-	
remove slab on grade	800	st	3.00	2,400		
temp shore / barricades	1	sum	25,000.00	25,000		
misc. support / cut / patch	14	sum	1,500.00	21,000		allowance
haul & disposal	1	sum	7,497.60	7,498	<b>*==</b> 100	-
Sub-total	90,384	sf	0.64	/sf	\$57,482	
Earthwork						
excavate for footing, neat cut	94	су	\$50.00	\$4,700		
haul & disposal	94	су	12.00	1,128		
Sub-total	90,384	sf	0.06	/sf	\$5,828	
Piling						
mobilization	1	sum	\$3.500.00	\$3.500	)	
100 ton micro piles	96	ea	3.000.00	288.000	)	
Sub-total	90,384	sf	3.23	/sf	\$291,500	-
Concrete work						
formwork						
footings		sf	\$0.00	\$0		NIC - assume earth form
walls	4 704	sf	10.00	47 040		
collector beam	2 240	sf	11.50	25 760		
spandrel beam	830	sf	11.00	9 545		
r/s	000	01	11.00	0,040	, ,	
footings	11 750	lhs	0.95	11 163	1	
walls	26 750	lbe	0.95	25 /12		
collector beam	10,000	lbe	0.00	9 500		
spandrel beam	3 000	lbs	0.95	2,850		
drill / dowol / coro	3,000	103	0.55	2,000		
	108	00	25.00	4 050		
core elevated slab for shear wall steel	190	letas	5 000 00	20,000		
dowel shear well to reaf slab	4	lotos	3,000.00	20,000		
dowel sileat wall to tool slab	290		2,000.00	14,000		
dowel collector beam ( connections	200	ll If	50.00	14,000		allowance
rodi mix	100		75.00	12,000		allowalice
1000 ppi	200	<u></u>	105.00	20 450		
	290	Cy	105.00	30,450		
place	00		25.00	0.450		
rooungs	98	су	25.00	2,450		
walls	107	cy	90.00	9,630		
	66	cy	115.00	7,590		
	19	су	115.00	2,185		
pump / transport concrete finish	290	су	30.00	8,700	1	
footing / slab finish	800	sf	0.65	520	)	
wall - break ties / patch	4,704	sf	2.25	10,584	Ļ	
misc.	1	sum	5.000.00	5.000	)	
Sub-total	90,384	sf	2.96	/sf	\$267,330	1
Non-structural						
connections in anchoring precast panels	1.644	lf	100.00	\$164.400	)	allowance
Sub-total	90.384	sf	1 82	/sf	\$164,400	
	50,004	<b>.</b> .	1.02		<i></i> , 100	

Salem Central Public Library	Ar	chitect	LLC	Estimate Date:	R27-Jab-14		
Seismic Upgrade Evaluation Report		S	tanley J. Pszczolk	owski, AIA		Document Date:	20-Dec-13
City of Salem, Oregon		806	0 SW Pfaffle Stre	et, Suite 110		Print Date:	27-Jan-14
BergerABAM		-	Tigard, Oregon 97	223-8489		Print Time:	1:16 PM
Evaluation Report Probable Cost Estimate - 1.2	Phone (50	03) 718-0	075 Fax (503) 7	18-0077 www.a	irchcost.com	Constr. Start:	Winter 2016
Alternates	Quantity	Unit	Cost / Unit	Cost	Sub-totals	Comm	ents
SUB-TOTAL 03   Parking Garage				786,540	\$786,540		
Estimating Contingency Index To Construction Start General Conditions / Insurance / Bond General Contractor OH & Profit	Winter 2016		15.00% 7.12% 9.50% 3.50%	117,981 64,402 92,048 37,134	311,565	@ ± 4% per year per BergerAbam per BergerAbam	39.61%
TOTAL DIRECT CONSTRUCTION COST 03   Parking Garage	90,384	sf	\$12.15	/sf	\$1,098,105		

Evaluation Report Salem Central Public Library City of Salem, Salem, Oregon

# Appendix C Proposed Renovation Drawings
















Evaluation Report Salem Central Public Library City of Salem, Salem, Oregon

> Appendix D Site Photographs



Photo 1 - West Wall of Building



Photo 2 - West Wall of Building, Mezzanine Level Children's Reading Area



Photo 3 - West Wall of Main Building, Mezzanine Level Children's Reading Area



Photo 4 - Southwest Corner of Main Building



Photo 5 - South Wall of Main Building



Photo 6 - South Entrance to Main Building



Photo 7 - Intersection of Main Building and Auditorium at South Side of Main Building



Photo 8 - Northwest Corner of Building



Photo 9 - North Side of Building



Photo 10 - North Side of Building



Photo 11 - North Side of Building



Photo 12 - Northeast Corner of Building



Photo 13 - East Side of Building



Photo 14 - East Side of Building



Photo 15 - East Side of Building



Photo 16 - East Side of Building – Shows Intersection of Auditorium with Main Building



Photo 17 - East Side of Building – Auditorium Exterior Walls



Photo 18 - Southeast Side of Building



Photo 19 - Southeast Side of Building



Photo 20 - West Side of Auditorium



Photo 21 - Intersection of Auditorium and Main Building at Roof Level



Photo 22 - Auditorium Roof Looking Southeast from Main Building Roof



Photo 23 - Interior of Main Library Building



Photo 24 - Shows Inadequately Braced Book Stacks



Photo 25 - Inadequately Braced Book Stacks



Photo 26 - View of the Main Level from the Second Story

## MAIN BUILDING AND AUDITORIUM - PHOTOS OF INTERIOR



Photo 27 - View of the Main Level from the Second Story



**Photo 28 - Inadequately Braced Shelves** 



Photo 29 - Unbraced Suspended Ceiling System and Piping



Photo 30 - Inadequately Braced Light Fixtures in Suspended Grid Ceilings



Photo 31 - Inadequately Braced Suspended Equipment



Photo 32 – Inadequately Braced Suspended Equipment



Photo 33 - Inadequately Braced Suspended Piping Systems



Photo 34 - Inadequately Braced Shelves



Photo 35 - Inadequately Braced Shelves



Photo 36 – Inadequately Braced Shelves



Photo 37 - Inadequately Braced Lockers



Photo 38 – Inadequately Braced Shelves



Photo 39 - Inadequately Braced Ladder



Photo 40 - Inadequately Braced Mechanical Equipment



Photo 41 - Inadequately Braced Mechanical Equipment



Photo 42 - Inadequately Braced Mechanical Equipment



Photo 43 - Inadequately Braced Mechanical Equipment



Photo 44 - Inadequately Braced Mechanical Equipment



Photo 45 - Inadequately Braced Suspended Mechanical Equipment



Photo 46 - Inadequately Braced Suspended Mechanical Equipment



Photo 47 - Inadequately Braced Mechanical Equipment



Photo 48 - Inadequately Braced Suspended Mechanical Equipment



Photo 49 - Inadequately Braced Suspended Mechanical Equipment



Photo 50 - Inadequately Braced Cabinets



Photo 51 - Adequately Braced Water Main Line



Photo 52 - Inadequately Braced Shelves



Photo 53 - Interior of Auditorium



Photo 54 - Upper Level Looking West



Photo 55 - Upper Level Looking West



Photo 56 - North Side of Parking Garage



Photo 57 - North Side of Parking Garage (SE Corner)



Photo 58 - East Side of Parking Garage (SE Corner)



Photo 59 - Parking Garage Looking North (NE Corner)


Photo 60 - Southwest Corner of Parking



Photo 61 - West Side of Parking Garage



Photo 62 - West Side of Parking Garage



Photo 63 - North Side of Parking Garage



Photo 64 - Northwest corner of Parking Garage



Photo 65 - Northwest corner of Parking Garage



Photo 66 - Interior of Parking Garage



Photo 67 - Interior of Parking Garage



Photo 68 - Interior of Parking Garage



Photo 69 - Interior of Parking Garage



Photo 70 - Interior of Parking Garage



Photo 71 - Interior of Parking Garage



Photo 72 - Interior of Parking Garage



Photo 73 - Interior of Parking Garage



Photo 74 - Interior of Parking Garage



Photo 75 - Interior of Parking Garage



Photo 76 - Interior of Parking Garage

Evaluation Report Salem Central Public Library City of Salem, Salem, Oregon

Appendix E ASCE 31-03 Tier 1 Checklists

### Seismic Design

Address: 585 Liberty Street SE, Salem, OR 97301-3513



Conterminous 48 States 2003 NEHRP Seismic Design Provisions Latitude = 44.935191 Longitude = -123.04129600000002 Spectral Response Accelerations Ss and S1 Ss and S1 = Mapped Spectral Acceleration Values Site Class B - Fa = 1.0 ,Fv = 1.0 Data are based on a 0.01 deg grid spacing Period Sa (sec) (g) 0.2 0.795 (Ss, Site Class B) 1.0 0.341 (S1, Site Class B)

Conterminous 48 States 2003 NEHRP Seismic Design Provisions Latitude = 44.935191 Longitude = -123.04129600000002 Spectral Response Accelerations SMs and SM1 SMs = Fa x Ss and SM1 = Fv x S1 Site Class D - Fa = 1.182 ,Fv = 1.717

Period Sa (sec) (g) 0.2 0.940 (SMs, Site Class D) 1.0 0.586 (SM1, Site Class D) Conterminous 48 States 2003 NEHRP Seismic Design Provisions Latitude = 44.935191 Longitude = -123.04129600000002 Design Spectral Response Accelerations SDs and SD1 SDs = 2/3 x SMs and SD1 = 2/3 x SM1 Site Class D - Fa = 1.182 ,Fv = 1.717

Period Sa (sec) (g) 0.2 0.626 (SDs, Site Class D) 1.0 0.391 (SD1, Site Class D)

#### Salem Central Public Library ASCE 31-03 Seismic Evaluation Checklists: MAIN BUILDING

- 3.7.9 Basic Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragms
- 3.7.9S Supplemental Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragms
- 3.8 Geologic Site Hazards and Foundations Checklist
- 3.9.1 Basic Nonstructural Component Checklist
- 3.9.2 Intermediate Nonstructural Component Checklist

#### 3.7.9 Basic Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragms

This Basic Structural Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier I Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С	NC	N/A	Building System
			LOAD PATH: The structure shall contain a minimum of one complete load path for Life Safety and Immediate Occupancy for seismic force effects from any horizontal direction that serves to transfer the inertial forces from the mass to the foundation. (Tier 2: Sec. 4.3.1.1)
			COMMENTS:
			MEZZANINES: Interior mezzanine levels shall be braced independently from the main structure, or shall be anchored to the lateral-force-resisting elements of the main structure. (Tier 2: Sec. 4.3.1.3)
			COMMENTS:
			WEAK STORY: The strength of the lateral-force-resisting system in any story shall not be less than 80 percent of the strength in an adjacent story, above or below, for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.1)
			<b>COMMENTS:</b> By inspection, the second level is a weak story. There is a significant reduction in both the number and length of lateral-force-resisting elements.
			SOFT STORY: The stiffness of the lateral-force-resisting system in any story shall not be less than 70 percent of the lateral-force-resisting system stiffness in an adjacent story above or below, or less than 80 percent of the average lateral-force-resisting system stiffness of the three stories above or below for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.2)
			<b>COMMENTS:</b> The stiffness of the lateral-force-resisting system at the second level is less than 70% the stiffness of the lateral-force-resisting system at the main level. This is obvious due to two factors, 1) There is a large open air space and 2) there is a significant reduction in stiff lateral-force-resisting elements between levels.
			GEOMETRY: There shall be no changes in horizontal dimension of the lateral-force- resisting system of more than 30 percent in a story relative to adjacent stories for Life Safety and Immediate Occupancy, excluding one-story penthouses and mezzanines. (Tier 2: Sec. 4.3.2.3)
			COMMENTS:
$\boxtimes$			VERTICAL DISCONTINUITIES: All vertical elements in the lateral-force-resisting system shall be continuous to the foundation. (Tier 2: Sec. 4.3.2.4)
			COMMENTS:

 $\boxtimes$ · · · · MASS: There shall be no change in effective mass more than 50 percent from one story to the next for Life Safety and Immediate Occupancy. Light roofs, penthouses, and mezzanines need not be considered. (Tier 2: Sec. 4.3.2.5) **COMMENTS:**  $\boxtimes$ TORSION: The estimated distance between the story center of mass and the story center of rigidity shall be less than 20 percent of the building width in either plan dimension for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.6) **COMMENTS:** At the main level, the estimated distance between the story center of mass and the story center of rigidity is approximately 35 feet. 20% of the building width in the N-S direction is approximately 33 feet. It appears that the building may have inherent torsional issues.  $\boxtimes$ DETERIORATION OF CONCRETE: There shall be no visible deterioration of concrete or  $\square$ reinforcing steel in any of the vertical- or lateral-force-resisting elements. (Tier 2: Sec. 4.3.3.4) **COMMENTS:** POST-TENSIONING ANCHORS: There shall be no evidence of corrosion or spalling in the  $\square$ vicinity of post-tensioning or end fittings. Coil anchors shall not have been used. (Tier 2: Sec. 4.3.3.5) **COMMENTS:**  $\boxtimes$  $\square$ CONCRETE WALL CRACKS: All Existing diagonal cracks in wall elements shall be less П than 1/8 inch for Life Safety and 1/16 inch for Immediate Occupancy, shall not be concentrated in one location, and shall not form an X pattern. (Tier 2: Sec. 4.3.3.9) **COMMENTS:** С NC N/A Lateral-Force-Resisting\_System  $\boxtimes$ П COMPLETE FRAMES: Steel or concrete frames classified as secondary components shall form a complete vertical-load-carrying system. (Tier 2: Sec. 4.4.1.6.1) **COMMENTS:**  $\boxtimes$ REDUNDANCY: The number of lines of moment frames in each principal direction shall be  $\square$ greater than or equal to 2 for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.1.1) **COMMENTS:** 

 $\square$ 

 $\square$ 

A14.0170.01

SHEAR STRESS CHECK: The shear stress in the concrete shear walls, calculated using the Quick Check procedure of Section 3.5.3.3, shall be less than the greater of 100 psi or  $2\sqrt{f}$  c for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.1)

**COMMENTS:** The demand-to-capacity ratio is greater than 1.0 (DCR = 1.44) for the second level only, in the E-W direction of loading.

 $\boxtimes$ 

 $\boxtimes$ 

REINFORCING STEEL: The ratio of reinforcing steel area to gross concrete area shall be not less than 0.0015 in the vertical direction and 0.0025 in the horizontal direction for Life Safety and Immediate Occupancy. The spacing of reinforcing steel shall be equal to or less than 18 inches for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.2

**COMMENTS:** Based on original construction drawings, rebar in the horizontal direction is less than the recommended 0.0025. Rebar in the vertical direction appears to be sufficient. For the 8" south stairwell walls, the plans show the horizontal rebar spaced at 20" O.C. which is larger than the 18" maximum rebar spacing.

C NC N/A

 $\boxtimes$ 

 $\boxtimes$ 

#### Connections

TRANSFER TO SHEAR WALLS: Diaphragms shall be connected for transfer of loads to the shear walls for Life Safety and the connections shall be able to develop the lesser of the shear strength of the walls or diaphragms for Immediate Occupancy. (Tier 2: Sec. 4.6.2.1)

**COMMENTS:** 

FOUNDATION DOWELS: Wall reinforcement shall be doweled into the foundation for Life Safety, and the dowels shall be able to develop the lesser of the strength of the walls or the uplift capacity of the foundation for Immediate Occupancy. (Tier 2: Sec. 4.6.3.5)

COMMENTS:

j.

#### 3.7.98 Supp. Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragm

This Supplemental Structural Checklist shall be completed where required by Table 3-2. The Basic Structural Checklist shall be completed prior to completing this Supplemental Structural Checklist.

С	NC	N/A	Lateral-Force-Resisting System		
			DEFLECTION COMPATIBILITY: Secondary components shall have the shear capacity to develop the flexural strength of the components for Life Safety and shall meet the requirements of Sections 4.4.1.5.9, 4.4.1.4.10, 4.4.1.4.11, 4.4.1.4.12 and 4.4.1.4.15 for Immediate Occupancy (Tier 2: Sec. 4.4.1.6.2)		
			<b>COMMENTS:</b> The 24" x 24" reinforced columns do not have enough horizontal reinforcement to resist the shear demand when the maximum moment, Mpr is applied. The shear demand is roughly 92 kips and the (E) column capacity, with #3 @ 16" O.C., is 50 kips.		
		$\boxtimes$	FLAT SLABS: Flat slabs/plates not part of the lateral-force-resisting system shall have continuous bottom steel through the column joints for Life Safety and Immediate Occupancy. (Tier 2: 4.4.1.6.3)		
			COMMENTS:		
			COUPLING BEAMS: The stirrups in coupling beams over means of egress shall be spaced at or less than d/2 and shall be anchored into the confined core of the beam with hooks of 135° or more for Life Safety. All coupling beams shall comply with the requirements above and shall have the capacity in shear to develop the uplift capacity of the adjacent wall for Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.3)		
			COMMENTS:		
			OVERTURNING: All shear walls shall have aspect ratios less than 4-to-1. Wall piers need not be considered. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.4)		
			COMMENTS:		
			CONFINEMENT REINFORCING: For shear walls with aspect ratios greater than 2-to-1, the boundary elements shall be confined with spirals or ties with spacing less than $8d_b$ . This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.5)		
			COMMENTS:		
$\boxtimes$			REINFORCING AT OPENININGS: There shall be added trim reinforcement around all wall openings with a dimension greater than three times the thickness of the wall. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.6)		
			COMMENTS:		
			WALL THICKNESS: Thickness of bearing walls shall not be less than 1/25 the unsupported height or length, whichever is shorter, nor less than 4 inches. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.7)		

.

Į

Screening Phase (Tier 1)

#### COMMENTS:

С	NC	N/A	Diaphragms	
			DIAPHRAGM CONTINUITY: The diaphragms shall not be composed of split-level floors and shall not have expansion joints. (Tier 2: Sec. 4.5.1.1)	
			COMMENTS:	
$\boxtimes$			OPENINGS AT SHEAR WALLS: Diaphragm openings immediately adjacent to the shear walls shall be less than 25 percent of the wall length for Life Safety and 15 percent of the wall length for Immediate Occupancy. (Tier 2: Sec. 4.5.1.4)	
			COMMENTS:	
			PLAN IRREGULITIES: There shall be tensile capacity to develop the strength of the diaphragm at re-entrant corners or other locations of plan irregularities. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.1.7)	
			COMMENTS:	
			DIAPHRAGM REINFORCEMENT AT OPENINGS: There shall be reinforcing around all diaphragm openings larger than 50 percent of the building width in either major plan dimension. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.1.7)	
			COMMENTS:	
С	NC	N/A	Connections	
			UPLIFT AT PILE CAPS: Pile caps shall have top reinforcement and piles shall be anchored to the pile caps for Life Safety, and the pile cap reinforcement and pile anchorage shall be able to develop the tensile capacity of the piles for Immediate Occupancy. (Tier 2: Sec. 4.6.3.10)	

#### **COMMENTS:**

#### 3.8 Geologic Site Hazards and Foundations Checklist

Geologic Site Hazards and Foundations Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

~			Geologic Site Hazards
_ <u>C</u>	NC	N/A	
			LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance shall not exist in the foundation soils at depths within 50 feet under the building for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.7.1.1)
			COMMENTS: Could not be verified.
			SLOPE FAILURE: The building site shall be sufficiently remote from potential earthquake- induced slope failures or rockfalls to be unaffected by such failures or shall be capable of accommodating any predicted movements without failure. (Tier 2: Sec. 4.7.1.2)
			COMMENTS:
			SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site is not anticipated. (Tier 2: Sec. 4.7.1.3)
			COMMENTS: Could not be verified.
С	NC	N/A	Condition of Foundations
×.			FOUNDATION PERFORMANCE: There shall be no evidence of excessive foundation movement such as settlement or heave that would affect the integrity or strength of the structure. (Tier 2: Sec. 4.7.2.1)
			COMMENTS:
			DETERIORATION: There shall not be evidence that foundation elements have deteriorated due to corrosion, sulfate attack, material breakdown, or other reasons in a manner that would affect the integrity or strength of the structure. (Tier 2: Sec. 4.7.2.2)
			COMMENTS: Could not be verified.

**Capacity of Foundations** NC С N/A  $\boxtimes$ POLE FOUNDATIONS: Pole foundations shall have a minimum embedment depth of 4 feet for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.7.3.1) **COMMENTS:**  $\boxtimes$  $\square$  $\square$ OVERTURNING: The ratio of the horizontal dimension of the lateral-force-resisting system at the foundation level to the building height (base/height) shall be greater than  $0.6S_a$ . (Tier 2: Sec. 4.7.3.2) **COMMENTS:**  $\boxtimes$ TIES BETWEEN FOUNDATION ELEMENTS: The foundation shall have ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Class A, B, or C. (Section 3.5.2.3.1, Tier 2: Sec. 4.7.3.3) **COMMENTS:**  $\boxtimes$ DEEP FOUNDATIONS: Piles and piers shall be capable of transferring the lateral forces between the structure and the soil. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.7.3.4) **COMMENTS:**  $\square$  $\square$ SLOPING SITES: The difference in foundation embedment depth from one side of the building to another shall not exceed one story in height. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.7.3.5)

#### COMMENTS:

Screening Phase (Tier 1) – Basic Nonstructural Component

#### 3.9.1 Basic Nonstructural Component Checklist

This Basic Nonstructural Component Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С	NC	N/A	Partitions	
			UNREINFORCED MASONRY: Unreinforced Masonry or hollow clay tile partitions shall be braced at spacing equal to or less than 10 feet in levels of low or moderate seismicity and 6 feet in levels of high seismicity. (Tier 2: Sec. 4.8.1.1)	
			<b>COMMENTS:</b> According to original construction drawings, the 8" concrete block walls located in both the mechanical room area and loading dock area have vertical reinforcement (#4 @ 4'-0" O.C.) and are doweled into the footing below by #4 @ 4'-0" O.C. and into the waffle slab above by #8 @ 4'-0" O.C.	
С	NC	N/A	Ceiling Systems	
			SUPPORT: The integrated suspended ceiling system shall not be used to laterally support the tops of gypsum board, masonry, or hollow clay tile partitions. Gypsum board partitions need not be evaluated where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.3.1)	
			COMMENTS:	
С	NC	N/A	Light Fixtures	
$\boxtimes$			EMERGENCY LIGHTING: Emergency lighting shall be anchored or braced to prevent falling during an earthquake. (Tier 2: Sec 4.8.3.1)	
			COMMENTS:	
С	NC	N/A	Cladding and Glazing	
			CLADDING ANCHORS: Cladding components weighing more than 10 psf shall be mechanically anchored to the exterior wall framing at a spacing equal to or less than 4 feet. A spacing of up to 6 feet is permitted where only Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.1)	
			<b>COMMENTS:</b> The precast concrete fascia panels on the exterior of the roof of the original building are anchored at 7'-6" O.C. The precast concrete fascia panels on the exterior of the 1990 expansion part of the building are anchored where the steel framing meets the concrete panels at roughly 8'-0" O.C. It is unclear from the plans how the relocated window/wall system on the north side of the building is attached to the main structure. Further investigation would be required to verify adequate anchorage.	
$\boxtimes$			DETERIORATION: There shall be no evidence of deterioration, damage or corrosion in any of the connection elements. (Tier 2: Sec. 4.8.4.2)	
			COMMENTS:	

Main Building			Screening Phase (Tier 1) – Basic Nonstructural Component A14.	0170.00
			CLADDING ISOLATION: For moment frame buildings of steel or concrete, panel connections shall be detailed to accommodate a story drift ratio of 0.02. Panel connect detailing for a story drift ratio of 0.01 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.3)	ion
			COMMENTS:	
			MULTI-STORY PANELS: For multi-story panels attached at each floor level, panel connections shall be detailed to accommodate a story drift ratio of 0.02. Panel connect detailing for a story drift ratio of 0.01 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.4)	ion
			COMMENTS:	
		$\boxtimes$	BEARING CONNECTIONS: Where bearing connections are required, there shall be a minimum of two bearing connections for each wall panel. (Tier 2: Sec. 4.8.4.5)	
			COMMENTS	
$\boxtimes$			INSERTS: Where inserts are used in concrete connections, the inserts shall be anchored reinforcing steel or other positive anchorage. (Tier 2: Sec. 4.8.4.6)	d to
			COMMENTS:	
			PANEL CONNECTIONS: Exterior cladding panels shall be anchored out-of-plane wit minimum of 4 connections for each wall panel. Two connections per wall panel are permitted where only the Basic Nonstandard Component Checklist is required by Table (Tier 2: Sec. 4.8.4.7)	h a e 3-2.
			COMMENTS:	
С	NC	N/A	Masonry Veneer	
			SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other element each floor 30 feet or more above ground for Life Safety and at each floor above the firs for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)	s at t floor
			COMMENTS:	
			TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for e 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2)	The every
		٢	COMMENTS:	
			WEAKENED PLANES: Masonry veneer shall be anchored to the backup adjacent to weakened planes, such as at the locations of flashing. (Tier 2: Sec. 4.8.5.3)	
			COMMENTS:	

Main Building			Screening Phase (Tier 1) – Basic Nonstructural Component A14.0170.00
			DETERIORATION: There shall be no evidence of deterioration, damage, or corrosion in any part of the connection elements. (Tier 2: Sec. 4.8.5.4) COMMENTS:
С	NC	N/A	Parapets, Cornices, Ornamentation, and Appendages
			URM PARAPETS: There shall be no laterally unsupported unreinforced masonry parapets or cornices with height-to-thickness ratios greater than 1.5. A height to thickness ratio of up to 2.5 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.8.1)
			COMMENTS:
			CANOPIES: Canopies located at building exits shall be anchored to the structural framing at a spacing of 6 feet or less. An anchorage spacing of up to 10 feet is permitted where only Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.8.2)
			COMMENTS:
С	NC	N/A	Masonry Chimneys
			URM CHIMNEYS: No unreinforced masonry chimney shall extend above the roof surface more than twice the least dimension of the chimney. A height above the roof surface up to three times the least dimension of the chimney is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.9.1)
			COMMENTS:
С	NC	N/A	Stairs
			URM WALLS: Walls around stair enclosures shall not consist of unbraced hollow clay tile or unreinforced masonry with a height-to-thickness ratio greater than 12-to-1. A height-to-thickness ratio of up to 15-to-1 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.10.1)
			COMMENTS:
			STAIR DETAILS: In moment frame structures, the connection between the stairs and the structure shall not rely on shallow anchors in concrete. Alternatively, the stair details shall be capable of accommodating the drift calculated using the Quick Check procedure of Section 3.5.3.1 without including tension in the anchors. (Tier 2: Sec. 4.8.10.2) <b>COMMENTS:</b>
			COMMENTS:

.

С	NC	N/A		
			Building Contents and Furnishing	
			TALL NARROW CONTENTS: Contents over 4 feet in height with a height-to-depth or height-to-width ratio greater than 3-to-1 shall be anchored to the floor slab or adjacent structural walls. A height-to-depth or height-to width ratio of up to 4-to-1 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.11.1)	
			<b>COMMENTS:</b> Unbraced shelving units, file cabinets, lockers and other miscellaneous furniture with a height-to-width or a height-to-depth ratio greater than 3-to-1 are present on all levels of the Main Building.	
C	NC	N/A	Mechanical and Electrical Equipment	
$\square$			EMERGENCY POWER: Equipment used as part of an emergency power system shall be mounted to maintain continued operation after an earthquake. (Tier 2: Sec. 4.8.12.1)	
			COMMENTS:	
			HAZARDOUS MATERIAL EQUIPMENT: HVAC or other equipment containing material shall not have damaged supply lines or unbraced isolation supports. (Tier 2: Sec. 4.8.12.2)	
			COMMENTS:	
	$\boxtimes$		DETERIORATION: There shall be no evidence of deterioration, damage, or corrosion in any of the anchorage or supports of mechanical or electrical equipment. (Tier 2: Sec. 4.8.12.3)	
			<b>COMMENTS:</b> There is corrosion on the anchorage supports of many pumps in the mechanical room. There is also significant corrosion on steel pipes in the mechanical room area of the building.	
	$\boxtimes$		ATTACHED EQUIPMENT: Equipment weighing over 20 lb that is attached to ceilings, walls, or other supports 4 feet above the floor level shall be braced. (Tier 2: Sec. 4.8.12.4)	
			<b>COMMENTS:</b> There are several pieces of equipment weighing over 20 lb. that are either attached to the ceilings or to walls that are not laterally braced. There are many areas throughout the entire building where the duct and piping, including the suspended ceiling system itself, does not appear to have lateral bracing which means that it could sway during an earthquake causing damage on impact with other adjacent items or may result in falling hazards to human life.	
С	NC	N/A	Piping	
			FIRE SUPPRESSION PIPING: Fire suppression piping shall be anchored and braced in accordance NFPA-13 (NFPA, 1996). (Tier 2: Sec. 4.8.13.1)	
			<b>COMMENTS:</b> There appears to be inadequate lateral bracing of both sprinkler heads and piping, along with areas where the impact of sprinkler pipes and other unbraced nonstructural elements could result in unreliable performance. Fire sprinkler piping has performed poorly in past earthquakes, rendering systems unusable when most needed.	

Main Building			Screening Phase (Tier 1) – Basic Nonstructural Component	A14.0170.00
			<ul> <li>FLEXIBLE COUPLINGS: Fluid, gas, and fire suppression piping shall have flex couplings. (Tier 2: Sec. 4.8.13.2)</li> <li>COMMENTS: Gas pipes do not appear to have flexible couplings which could 1 fracture in an earthquake event.</li> </ul>	ible ead to a
c X		N/A	Hazardous Materials Storage and Distribution TOXIC SUBSTANCES: Toxic and hazardous substances stored in breakable con be restrained from falling by latched doors, shelf lips, wires, or other methods. (7 4.8.15.1)	itainers shall Fier 2: Sec.
			COMMENTS:	

-

#### 3.9.2 Intermediate Nonstructural Component Checklist

This Intermediate Nonstructural Component Checklist shall be completed where required by Table 3-2. The Basic Nonstructural Component Checklist shall be completed prior to completing this Intermediate Nonstructural Component Checklist.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С	NC	N/A	Ceiling Systems
			LAY-IN TILES: Lay-in tiles used in ceiling panels located at exits and corridors shall be secured with clips. (Tier 2: Sec. 4.8.2.2)
			COMMENTS:
			INTEGRATED CEILINGS: Integrated suspended ceilings at exits and corridors or weighing more than 2 pounds per square foot shall be laterally restrained with a minimum of four diagonal wires or rigid members attached to the structure above at a spacing equal to or less than 12 feet. (Tier 2: Sec. 4.8.2.4)
		۰.	<b>COMMENTS:</b> There appears to be no lateral bracing in many areas throughout the building.
			SUSPENDED LATH AND PLASTER: Ceilings consisting of suspended lath and plaster or gypsum board shall be attached to resist seismic forces for every 12 square feet of area. (Tier 2: Sec. 4.8.2.4)
		•	<b>COMMENTS:</b> It is under our impression that the suspended lath and plaster ceilings shown on the plans for the original building construction in 1970 were removed and replaced during the 1990 expansion upgrade.
С	NC	N/A	Light Fixtures
			INDEPENDENT SUPPORT: Light fixtures in suspended grid ceilings shall be supported independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2)
			<b>COMMENTS:</b> The light fixtures in the suspended grid ceiling are not supported independently of the ceiling suspension system.
С	NC	N/A	Cladding and Glazing
			GLAZING: Glazing in curtain walls and individual panes over 16 square feet in area, located up to a height of 10 feet above an exterior walking surface, shall have safety glazing. Such glazing located over 10 feet above exterior walking surface shall be laminated annealed or laminated heat-strengthened safety glass or other glazing system that will remain in the frame when glass is cracked. (Tier 2: Sec. 4.8.4.8)
			<b>COMMENTS:</b> Glass from original building does not appear to be safety glass. In addition, the connection of glass to structure does not allow for relative displacement.

Main Building			Screening Phase (Tier 1) – Intermediate Nonstructural Component A14.0170.00	
С	NC	N/A	Parapets, Cornices, Ornamentation, and Appendages	
$\boxtimes$			CONCRETE PARAPETS: Concrete parapets with height-to-thickness ratios greater than 2.5 shall have vertical reinforcement. (Tier 2: Sec. 4.8.8.3)	
			COMMENTS	
			APPENDAGES: Cornices, parapets, signs, and other appendages that extend above the highest point of anchorage to the structure or cantilever from exterior wall faces and other exterior wall ornamentation shall be reinforced and anchored to the structural system at a spacing equal to or less than 10 feet for Life Safety and 6 feet for Immediate Occupancy. This requirement need not apply to parapets or cornices compliant with Section 4.8.8.1 or 4.8.8.3. (Tier 2: Sec. 4.8.8.4)	
			COMMENTS:	
С	ŃĊ	N/A	Masonry Chimneys	
			ANCHORAGE: Masonry chimneys shall be anchored at each floor level and the roof. (Tier 2: Sec. 4.8.9.2)	
			COMMENTS:	
С	NC	N/A	Mechanical and Electrical Equipment	
			VIBRATION ISOLATORS: Equipment mounted on vibration isolators shall be equipped with restraint or snubbers. (Tier 2: Sec. 4.8.12.5)	
			COMMENTS:	
С	NC	N/A	Ducts	
			STAIR AND SMOKE DUCTS: Stair pressurization and smoke control ducts shall be braced and shall have flexible connections at seismic joints. (Tier 2: Sec. 4.8.14.1)	
			COMMENTS:	

# Supporting Calculations

### Roof Loads (psf) - Main Building

	Flr. Mass
Insulation	1
5-Ply Felt and Gravel	6
Slab/Joist System (14" Waffle Slab + 3" concrete cover)	105
Suspended Ceiling	3
Mechanical and Electrical	8
Fire Sprinklers	1
Reinforced Concrete Columns	17
Exterior Walls	33
Miscellaneous	4
Dead Load	178
Live Load	20

### Roof Loads (psf) - 1990 Wing Addition

	Flr. Mass
Roofing (Metal deck + insullation)	4
Steel Framing	15
Suspended Ceiling	3
Exterior Walls	40
Mechanical and Electrical	5
Fire Sprinklers	1
Miscellaneous	2
Dead Load	70
Live Load	20

### Floor Loads (psf) - Main Building - Second Level

	Flr. Mass
Flooring	5
Slab/Joist System (14" waffle + 3" concrete cover)	105
Partitions/ non-bearing walls	10
Mechanical and Electrical	5
Fire Sprinklers	1
Reinforced Concrete Columns	36
Exterior Walls	50
Miscellaneous	5
Dead Load	217
Live Load (Library - Stacks)	150

### Floor Loads (psf) - Main Building - Main Level

	Flr. Mass
Flooring	5
Slab/Joist System (14" waffle + 3" concrete cover)	105
Partitions/ non-bearing walls	10
Mechanical and Electrical	10
Fire Sprinklers	1
Reinforced Concrete Columns	28
Exterior Walls	40
Miscellaneous	5
· · · · · · · · · · · · · · · · · · ·	
Dead Load	204
Live Load (Library - Stacks)	150

### Floor Loads (psf) - 1990 Wing Addition - Second Level

	Flr. Mass
Deck (metal decking + concrete)	54
Steel Framing	20
Partitions/ non-bearing walls	10
Mechanical and Electrical	5
Fire Sprinklers	1
Columns	1
Exterior Walls	50
Miscellaneous	4
Dead Load	145
Live Load (Lirary - Stacks)	20

### Floor Loads (psf) - 1990 Wing Addition - Main Level

	Flr. Mass
Deck (metal decking + concrete)	54
Steel Framing	20
Partitions/ non-bearing walls	10
Mechanical and Electrical	5
Fire Sprinklers	1
Columns	1
Exterior Walls	35
Miscellaneous	4
Dead Load	130
Live Load (Lirary - Stacks)	20

#### City of Salem, OR Mass Take Offs

### <u>Roof Level</u>

Location	plf	total linear ft	Weight, lbs
Roof Precast-Panels	525	710	372,750
Exterior Walls			
North Side of Building	550	· 196	107,800
West Side of Building	1,500	130 <sup>.</sup>	195,000
South Side of Building	550	196	107,800
East Side of Building	1,500	130	195,000
Interior Walls		· · · · · · · · · · · · · · · · · · ·	
8" Concrete Wall	660		
10" Concrete Wall	825		
· · · ·		Total Floor Weight =	978,350
· · · · · · · · · · · · · · · · · · ·	<i>i</i>	Total Floor psf=	32

### Second Level

Location	plf	total linear ft	Weight, lbs
Exterior Walls		-	
North Side of Building	950	196	186,200
West Side of Building	2,150	42	90,300
South Side of Building	950	65	61,750
East Side of Building	2,150	130	279,500
Interior Walls		· · · · · ·	
8" Concrete Wall	1,300		1
10" Concrete Wall	1,625		
Concrete Rail			
		Total Floor Weight =	617,750
		Total Floor psf=	47

### Main Level

Location	plf	total linear ft	Weight, lbs
Exterior Walls			
North Side of Building	980	196	192,080
West Side of Building (Open Area)	3,250	90	292,500
West Side of Building (Mezz Area)	2,000	40	80,000
South Side of Building	980	196	192,080
East Side of Building	2,000	130	260,000
Interior Walls			
8" Concrete Wall	. 1,225		
10" Concrete Wall	1,530		
· · · ·		Total Floor Weight =	1,016,660
		Total Floor psf=	40

#### A14.0170.00

### Main Building

	Roof I	Level	
Location	psf	total sf	Weight, lbs
1970 Original Building	178	30,745	5,472,610
1990 Wing Addition	70	8,300	581,000
		Total Floor Weight (lbs) =	6,053,610

		Ç,	_
Location	psf	total sf	Weight, lbs
1970 Original Building	217	13,225	2,869,825
1990 Wing Addition	145	8,300	1,203,500
· ·	Total F	loor Weight (lbs), DL=	4,073,325
Live	Load (25% x 150psi x T	otal SF = 12,000), lbs =	450,000
		Σ =	4,523,325

#### Second Level

### Main Level

Location	psf	total sf	Weight, lbs
1970 Original Building	204	25,640	5,230,560
1990 Wing Addition	130	8,300	1,079,000
	Tot	al Floor Weight (lbs) =	6,309,560
Live Load (25% x 150psi x Total SF = 20,000), lbs =		750,000	
		Σ =	7,059,560

Total Building Weight, Dead Load =	16,436	kips
Live Load (25% x 150psi x Total SF = 32,000) =	1,200	kips
Σ =	17,636	kips

f

•

### Building Period (T)

$T = (C_t)(h_n)^{\beta}$	
C <sub>t</sub> =	0.020 (For all other framing systems)
hn = 1	38 ft
β =	0.75 (For all other framing systems)
T =	0.306 seconds

#### Story Shear Forces (V)

#### V=CS<sub>a</sub>W

C =	1.1	(From ASCE 31 Table 3-4)
W =	17,636	kips (From mass take off calculations spreadsheets)

$S_a = S_{D1}/T$	1.277	g
S <sub>D1</sub> =	0.391	g

### $\rm S_a$ shall not exceed $\rm S_{\rm DS}$ Therefore:

S <sub>DS</sub> =	0.626 g
S <sub>a</sub> =	therefor: 0:626 g

Seismic Shear:

V =	0.689	*W	kips
V =	12	2,144	kips

## Shear Wall Area for Shear Stress in Concrete Shear Walls Quick Calc (3.5.3.3):

N-S Direction of Loading			
Location	Length, ft	Area, sf	
Main Level			
20" Ext. Column	112	187	
12" Wall	156	156	
10" Wall	198	165	
8" Wall	85	57	
Σ =	551	564	
Location	Length, ft	Area, sf	
Second Level			
20" Ext. Column	91	152	
12" Wall	27	27	
10" Wall	0	0	
8" Wall	70	47	
Σ =	188	225	
Location	Length, ft	Area, sf	
Roof Level	·		
20" Ext. Column	112	187	
12" Wall	27	27	
10". Wali	0	0	
8" Wall	70	47	
Σ =	209	260	

E-W Direction of Loading			
Location	Length, ft	Area, sf	
Main Level			
20" Ext. Column	70	117	
12" Wall	180	180	
10" Wall	205	171	
8" Wall	58	39	
Σ	= 513	506	
Location	Length, ft	Area, sf	
Second Level			
20" Ext. Column	0	0	
12" Wall	27	27	
10" Wall	10	8	
8" Wall	20	13	
Σ=	= 57	49	
Location	Length, ft	Area, sf	
Roof Level			
20" Ext. Column	70	117	
12" Wall	27	27	
10" Wall	10	8	
8" Wall	20	13	
Σ =	= 127	165	

### Story Shear Forces in Concrete Shear Walls (3.5.2.2):

Story	h <sub>x</sub>	w <sub>x</sub> (kips)	h <sub>x</sub> w <sub>x</sub> <sup>k</sup>	Cv	F <sub>x</sub> (kips)
Roof	38	6,054	230,052	0.519	6,307
Second Level	26	4,523	117,598	0.265	3,224
Main Level	13.5	7,060	95,310	0.215	2,613
		Σ	= 442,960	1.000	12.144

 $V_j = \sum_{i=j}^n F_x$ 

### Shear Stress in Concrete Shear Walls (3.5.3.3):

Determined as follows:

 $vj^{avg} = -$ 

$$\frac{1}{m} \left(\frac{V_j}{A_m}\right)$$
m = Component modification factor: Taken from table 3-7  
Vj = story shear  
Aw = Sum of horizontal cross-section areas of walls

Limit shear stress to greater of:

100psi 2√f'c or

$$2\sqrt{f'c} = 2 \times \sqrt{4000 \ psi} = 126 \ psi$$

126 psi CONTROLS 0.126 ksi CONTROLS

	N-S Direction						
	Story	A <sub>w</sub> (in <sup>2</sup> min)	V <sub>j</sub> (kips)	m	v <sub>j</sub> <sup>avg</sup> (ksi)	DCR	Less than?
	Roof	37,488	6,307	4.0	0.04	0.33	ОКАҮ
	Second Level*	32,448	9,531	4.0	0.07	0.53	ΟΚΑΥ
	Main Level	81,264	12,144	4.0	0.04	0.30	ΟΚΑΥ
	E-W Direction						
	Story	A <sub>w</sub> (in <sup>2</sup> min)	V <sub>j</sub> (kips)	m	v <sub>j</sub> <sup>avg</sup> (ksi)	DCR	Less than?
	Roof	23,808	6,307	4.0	0.07	0.53	ΟΚΑΥ
÷.,	Second Level*	7,008	9,531	4.0	0.18	1.44	NOT GOOD
	Main Level	72,888	12,144	4.0	0.04	0.33	ΟΚΑΥ

3,224 kips 6,307 kips \* viavg =  $A_{w(Roof)}$ w (2nd Level)

Note: All of the columns supporting the roof do not support the 2nd level.

DergerABAM	Project Salem Library subject i Main Bidg. Floor Weights	Sheetof Job Number_ <u>A14.D170.00</u> Designer_ <u>CMG</u> Date12-2013
Floor Weigh	ts (watche system)~	
* Assume * $2^{1}/2^{\prime} \times 2^{1}/2^{\prime}$ * Filled ar	14" Waffle + 3" topping 2' Voids ound columns (punchi	j= 17" total thk. ing shear)
-> <u>detern</u> 64' x Voi	<u>nine Aug. psf:</u> : 64' grid section = 4,096 ds = 6.25 s.f.	, , ,
tota	l concrete s.f. = 4,0965 - 6.25 s.f	s.f. F. (84 voids × 4 grids)=2,100 S.f
	~= 2,000 S	"f. × 17" thick
	~ 2,8 33	c.f. concrete
total	weight = 2,833 c.f. (1	50 p.c.f)
	$= 424,950^{\#}/4,0$	096 S.F. = 105 psf

.

Project Salem Library stream of the boundary Main Bida.  
Subset Main Bida.  
Subset Main Bida.  
Subset Mailes - Rose Pre-east parcels of thick a (General)  
Exterior Walls - Rose Pre-east parcels of thick a (General)  
concrete 
$$W_T + 150 \text{ pcf}$$
  
 $(6^{\prime\prime}/12^{\prime\prime})(7 \text{ H}) = 3.5 \text{ sf} (150 \text{ pcf}) = 525 \text{ p1f}$  (  
Exterior Walls - North Side of building -  
(measured between grid times)  
Boof  
Het (10° concrete wall  $\mathfrak{D}$  top) = 3.33 Sf.  
(Het (Window -> 8 psf)  
 $3.33 \text{ sf} (150 \text{ pcf}) = .500 \text{ p1f}$   
 $1.5 \text{ ptf} (Window -> 8 psf)$   
 $1.5 \text{ ptf} (Window -> 8 psf)$   
 $1.5 \text{ ptf} (Window -> 8 psf)$   
 $1.5 \text{ pt} (16 + 1) + 35 \text{ ptf} (10^{\prime\prime} concrete wall) = 6.5t$   
 $5\text{ ft} (Window -> 8 psf)$   
 $1.5 \text{ pt} (16 + 2) + 35 \text{ ptf} (10^{\prime\prime} concrete wall) = 6.5t$   
 $5\text{ ft} (Window -> 8 psf)$   
 $1.5 \text{ ft} (8 psf) = 12$   
 $3 \text{ sf} (150 \text{ pcf}) = .900 \text{ p1f}$   
 $5\text{ ft} (8 psf) = .12$   
 $3 \text{ ft} (16 \text{ pcf}) = .900 \text{ p1f}$   
 $5\text{ ft} (8 psf) = .12$   
 $3 \text{ ft} (16 \text{ pcf}) = .900 \text{ p1f}$   
 $5\text{ ft} (8 psf) = .12$   
 $3 \text{ ft} (16 \text{ pcf}) = .900 \text{ p1f}$   
 $5\text{ ft} (8 psf) = .12$   
 $3 \text{ ft} (16 \text{ pcf}) = .900 \text{ p1f}$   
 $5\text{ ft} (8 psf) = .12$   
 $3 \text{ ft} (16 \text{ pcf}) = .900 \text{ p1f}$   
 $5\text{ ft} (8 psf) = .12$   
 $3 \text{ ptf} (16 \text{ pcf}) = .40 \text{ p1f}$   
 $3 \text{ ft} (16 \text{ pcf}) = .40 \text{ p1f}$   
 $3 \text{ ft} (16 \text{ pcf}) = .40 \text{ p1f}$ 

1

(
Eng-001-062209

 $\langle \rangle$ 

.

\_\_\_)

ú

- -

-----

Main Bldg. Roof-

 $\int$ 

( )

$$\frac{\text{TRIB} = 6.6 \text{ ft}}{(24'' \times 24'') \times 11} = 44 \text{ sf}}$$

$$(24'' \times 24'') \times 3 = 20 \text{ sf}}$$

$$(20'' \times 7') \times 15 = 176 \text{ sf}}$$

$$\frac{\text{TRIB} = 13 \text{ ft}}{(24'' \times 24'') \times 4} = 16 \text{ sf}}$$

$$(24'' \times 24'') \times 4 = 16 \text{ sf}}$$

$$(20'' \times 7') \times 11 = \frac{130 \text{ sf}}{2} = 146 \text{ sf}}$$

$$\text{Total } W_{\tau} = \left[ (6.6 \text{ ft}) (240 \text{ sf}) + 13 \text{ ft} (146 \text{ sf}) \right] (150 \text{ pcf})$$

$$= 522,300 \text{ ft}}$$

$$\text{Total } Roof = 5.\text{F}, \cong 30,745$$

$$\text{``PSF} = 522,300^{\text{ft}} / 30,745 \text{ sf}, = 17 \text{ psf}}$$

Eng-001-062209

· · · · )



()

.

J

()

Proved Sale en Library  
The BergerABAM  
BergerABAM  
Based Main Building  
Quick Checks  
Date International Sector And Checks  
Date International Sector And Checks  
TRIB= 32' × 32' = 1,024 st.  
Total Load = 1.2D+ 1.0L = 1.2(204 psf) + 1.0(150 psf)  
= 395 psf  
OR 405 kip (worst catc)  
Sece Sp column out (nut, 
$$\phi = 1.0$$
,  $f'_{c=3000}$  psi  
(ACI)  
Demand)  $V = 2mpr = 2[031^{K-41}] = 105^{K}$   
(Demand)  $V = 2mpr = 2[031^{K-41}] = 105^{K}$   
(Capacity)  $V_{S} = A_{V}F_{V}d$   
 $H = 32 10'' O.C.$   
ACI eqn.11+15  
 $H = 12.21''$   
 $S = 0.72in^{2}(by0000050)(22.1'')$   
 $= 18.23^{K}$   
 $V_{c} = 2\sqrt{3}c'' bw d = 2\sqrt{3000005}(24^{O})(22.1'') = 58.1K$   
 $[\Phi V_{c} = 0.65(58.1^{K}) - 37.7^{K}]$ 

 $\langle \cdot \rangle$ 

()

STRUCTUREPOINT - spColumn v4.81 (TM) Licensed to: BergerABAM. License ID: 59529-1032107-4-1A81A-1E412 12/16/13 g:\portland\2014\a14.0170\01\engineering\cmg\report documents\seism...\interior column 24 x 24.col 01:01 PM General Information: File Name: q:\portland\2014\a14.0170\01\engineering\cmg\report docume...\interior column 24 x 24.col Project: Salam Library - Main Bldg Engineer: CMG Column: ACI 318-08 Code: Units: English Slenderness: Not considered Run Option: Investigation Run Axis: X-axis Column Type: Structural Material Properties: = 1.25 fy (PER ACI 21.4.5) = 75 ksi f'c = 4 ksi Ec = 3605 ksi fy Es = 29000 ksi Ec Ultimate strain = 0.003 in/in Beta1 = 0.85Section: \_\_\_\_\_ Rectangular: Width = 24 in Depth = 24 in Gross section area,  $Ag = 576 \text{ in}^2$  $Iy = 27648 in^{4}$  $Ix = 27648 in^4$ rx = 6.9282 inry = 6.9282 inYo = 0 in Xo = 0 in Reinforcement: \_\_\_\_\_\_\_ Bar Set: ASTM A615 Size Diam (in) Area (in^2) Size Diam (in) Area (in^2) Size Diam (in) Area (in^2) \_\_\_\_ \_ ---- ----- --------- ------ ----**--**-----#4 #7 0.11 0.50 0.20 # 5 0.63 0.31 # 3 0.38 0.60 # 0.44 1.00 0.88 8 1.00 0.75 0.79 # 6 1.27 2.26 # 9 # 10 # 11 1.41 1.13 1.56 2.25 # 18 4.00 # 14 1.69 Confinement: Other; #3 ties with #10 bars, #4 with larger bars. phi(a) = 1, phi(b) = 1, phi(c) = 0.65Layout: Rectangular Pattern: All Sides Equal (Cover to transverse reinforcement) Total steel area: As = 6.32 in<sup>2</sup> at rho = 1.10% Minimum clear spacing = 8.63 in 8 #8 Cover = 1.5 inAxial Load and Corresponding Moment Capacities:

Page

2

Load	PhiPn	PhiMnx	NA depth	Dt depth	eps_t	Phi
No.	kip	k-ft	in	in		
1	0.0	398.29	3.46	21.63	0.01577	1.000
		-398.29	3.46	21.63	0.01577	1.000
2	25.0	417.46	3.69	21.63	0.01459	1.000
		-417.46	3.69	21.63	0.01459	1.000
3	50.0	436.29	3.93	21.63	0.01350	1.000
		-436.29	3.93	21.63	0.01350	1.000
4	75.0	454.79	4.18	21.63	0.01251	1.000
		-454.79	4.18	21.63	0.01251	1.000
5	100.0	472.89	4.45	21.63	0.01160	1.000
		-472.89	4.45	21.63	0.01160	1.000
6	125.0	490.59	4.71	21.63	0.01076	1.000
		-490.59	4.71	21.63	0.01076	1.000
7	150.0	507.85	4.99	21.63	0.01000	1.000
		-507.85	4.99	21.63	0.01000	1.000
8	175.0	524.60	5.28	21.63	0.00930	1.000
		-524.60	5.28	21.63	0.00930	1.000
9	200.0	540.92	5.57	21.63	0.00865	1.000
		-540.92	5.57	21.63	0.00865	1.000
10	225.0	556.69	5.86	21.63	0.00807	1.000
		-556.69	5.86	21.63	0.00807	1.000
11	250.0	571.97	6.16	21.63	0.00752	1.000
		-571.97	6.16	21.63	0.00752	1.000
12	275.0	586.35	6.46	21.63	0.00704	1.000
		-586.35	6.46	21.63	0.00704	1.000
13	300.0	596.04	6.67	21.63	0.00672	1.000
		-596.04	6.67	21.63	0.00672	1.000
14	325.0	605.67	6.89	21.63	0.00642	1.000
		-605.67	6.89	21.63	0.00642	1.000

ŗ

15	350.0	615.17	7.11	21.63	0.00613	1.000
		-615.17	7.11	21.63	0.00613	1.000
16	375.0	624.55	7.34	21.63	0.00584	1.000
		-624.55	7.34	21.63	0.00584	1.000
17	400.0	633.79	7.57	21.63	0.00557	1.000
		-633.79	7.57	21.63	0.00557	1.000

.

\*\*\* End of output \*\*\*



Ec = 3605 ksi	Es = 29000 ksi
fc = 3.4 ksi	
e_u = 0.003 in/in	
Beta1 = 0.85	
Confinement: Other	
phi(a) = 1, phi(b) = 1, phi(c) =	0.65

Ag = 576 in^2

As = 6.32 in^2

Xo = 0.00 in

Yo = 0.00 in

rho = 1.10% lx = 27648 in^4 ly = 27648 in^4 Min clear spacing = 8.63 in Clear cover = 1.88 in

DergerABAM	Project <u>Salem Library</u> Subject <u>Main Bhuilding</u>	Sheetof Job Number_ <u>A14,0170,000</u> Designer_ <u>(MG</u> Date <u>12,17,13</u>
Check for c	overturning (geologic site	, hazard)~
0.65	a = 0.6 (0.626g) = 0	.376

ratio	base/height =	513ff =	13.5 >>0.38
		38 ft	So OK

,

( )

()

.

#### Salem Central Public Library ASCE 31-03 Seismic Evaluation Checklists: AUDITORIUM

- 3.7.9A Basic Structural Checklist for Building Type C2A: Concrete Shear Walls with Flexible Diaphragms
- 3.7.9AS Supplemental Structural Checklist for Building Type C2A: Concrete Shear Walls with Flexible Diaphragms
- 3.8 Geologic Site Hazards and Foundations Checklist

3.9.1 Basic Nonstructural Component Checklist

3.9.2 Intermediate Nonstructural Component Checklist

#### 3.7.9A Basic Structural Checklist for Building Type C2A: Concrete Shear Walls with Flexible Diaphragms

This Basic Structural Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier I Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С	NC	N/A	Building System
$\boxtimes$			LOAD PATH: The structure shall contain a minimum of one complete load path for Life Safety and Immediate Occupancy for seismic force effects from any horizontal direction that serves to transfer the inertial forces from the mass to the foundation. (Tier 2: Sec. 4.3.1.1)
			COMMENTS:
	$\boxtimes$		ADJACENT BUILDINGS: The clear distance between the building being evaluated and any adjacent building shall be greater than 4 percent of the height of the shorter building for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.1.2)
			<b>COMMENTS:</b> $4\%$ *H = 10 inches. There is no clear distance provided between the Auditorium and the adjacent buildings.
		$\boxtimes$	MEZZANINES: Interior mezzanine levels shall be braced independently from the main structure, or shall be anchored to the lateral-force-resisting elements of the main structure. (Tier 2: Sec. 4.3.1.3)
			COMMENTS:
			WEAK STORY: The strength of the lateral-force-resisting system in any story shall not be less than 80 percent of the strength in an adjacent story, above or below, for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.1)
			COMMENTS:
			SOFT STORY: The stiffness of the lateral-force-resisting system in any story shall not be less than 70 percent of the lateral-force-resisting system stiffness in an adjacent story above or below, or less than 80 percent of the average lateral-force-resisting system stiffness of the three stories above or below for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.2)
			COMMENTS:
			GEOMETRY: There shall be no changes in horizontal dimension of the lateral-force- resisting system of more than 30 percent in a story relative to adjacent stories for Life Safety and Immediate Occupancy, excluding one-story penthouses and mezzanines. (Tier 2: Sec. 4.3.2.3)
			COMMENTS:

r

	$\boxtimes$			VERTICAL DISCONTINUITIES: All vertical elements in the lateral-force-resisting system shall be continuous to the foundation. (Tier 2: Sec. 4.3.2.4)
				COMMENTS:
				MASS: There shall be no change in effective mass more than 50 percent from one story to the next for Life Safety and Immediate Occupancy. Light roofs, penthouses, and mezzanines need not be considered. (Tier 2: Sec. 4.3.2.5)
				COMMENTS:
		□.	$\boxtimes$	DETERIORATION OF WOOD: There shall be no signs of decay, shrinkage, splitting, fire damage, or sagging in any of the wood members and none of the metal connection hardware shall be deteriorated, broken, or loose. (Tier 2: Sec. 4.3.3.1)
				COMMENTS:
				DETERIORATION OF CONCRETE: There shall be no visible deterioration of concrete or reinforcing steel in any of the vertical- or lateral-force-resisting elements. (Tier 2: Sec. 4.3.3.4)
				COMMENTS:
			$\boxtimes$	POST-TENSIONING ANCHORS: There shall be no evidence of corrosion or spalling in the vicinity of post-tensioning or end fittings. Coil anchors shall not have been used. (Tier 2: Sec. 4.3.3.5)
				COMMENTS:
	$\boxtimes$			CONCRETE WALL CRACKS: All Existing diagonal cracks in wall elements shall be less than 1/8 inch for Life Safety and 1/16 inch for Immediate Occupancy, shall not be concentrated in one location, and shall not form an X pattern. (Tier 2: Sec. 4.3.3.9)
				COMMENTS:
	С	NC	N/A	Lateral-Force-Resisting System
_				REDUNDANCY: The number of lines of moment frames in each principal direction shall be greater than or equal to 2 for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.1.1)
				COMMENTS:
				SHEAR STRESS CHECK: The shear stress in the concrete columns, calculated using the Quick Check procedure of Section 3.5.3.2, shall be less than the greater of 100 psi or $2\sqrt{f^2}c$ for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.1)
				COMMENTS:

Auditorium	

-

			REINFORCING STEEL: The ratio of reinforcing steel area to gross concrete area shall be not less than 0.0015 in the vertical direction and 0.0025 in the horizontal direction for Life Safety and Immediate Occupancy. The spacing of reinforcing steel shall be equal to or less than 18 inches for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.2) <b>COMMENTS:</b> Based on original construction drawings, rebar in the horizontal direction is less than the recommended 0.0025 (ratio = 0.00208).
С	NC	N/A	Connections
			WALL ANCHORAGE: Exterior concrete or masonry walls that are dependent on the diaphragm for lateral support shall be anchored for out-of-plane forces at each diaphragm level with steel anchors, reinforcing dowels, or straps that are developed into the diaphragm. Connections shall have adequate strength to resist the connection force calculated in the Quick Check procedure of Section 3.5.3.7. (Tier 2: 4.6.1.1) <b>COMMENTS:</b> The original construction drawings show the roof deck attaching to the exterior 8" concrete walls via. (1) 5/8" Dia. x 5" wedge anchor @ 48" O.C. These anchors no longer meet current seismic code. However, to check the strength of the connection we compared the demand to the capacity of Hilti 5/8" Dia. KBII anchor bolts with a 4" embedment depth. From the ER-4627 report, the allowable tension load = 1,335 lbs. Our calculated demand, using tributary area approach = 1,975 lbs.
			TRANSFER TO SHEAR WALLS: Diaphragms shall be connected for transfer of loads to the shear walls for Life Safety and the connections shall be able to develop the lesser of the shear strength of the walls or diaphragms for Immediate Occupancy. (Tier 2: Sec. 4.6.2.1)
			COMMENTS:
$\boxtimes$			FOUNDATION DOWELS: Wall reinforcement shall be doweled into the foundation for Life Safety, and the dowels shall be able to develop the lesser of the strength of the walls or the uplift capacity of the foundation for Immediate Occupancy. (Tier 2: Sec. 4.6.3.5)

#### COMMENTS:

## 3.7.9AS Supplemental Structural Checklist for Building Type C2A: Concrete Shear Walls with Flexible Diaphragms

This Supplemental Structural Checklist shall be completed where required by Table 3-2. The Basic Structural Checklist shall be completed prior to completing this Supplemental Structural Checklist.

С	NC	N/A	Lateral-Force-Resisting System
			COUPLING BEAMS: The stirrups in coupling beams over means of egress shall be spaced at or less than $d/2$ and shall be anchored into the confined core of the beam with hooks of $135^{\circ}$ or more for Life Safety. All coupling beams shall comply with the requirements above and shall have the capacity in shear to develop the uplift capacity of the adjacent wall for Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.3)
			<b>COMMENTS:</b> The connection of the coupling beams does not include hooks of 135 degrees or more. According to the original construction drawings, all hooks are at 90 degree angles.
			OVERTURNING: All shear walls shall have aspect ratios less than 4-to-1. Wall piers need not be considered. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.4)
			COMMENTS:
			CONFINEMENT REINFORCING: For shear walls with aspect ratios greater than 2-to-1, the boundary elements shall be confined with spirals or ties with spacing less than $8d_b$ . This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.5)
			COMMENTS:
			REINFORCING AT OPENININGS: There shall be added trim reinforcement around all wall openings with a dimension greater than three times the thickness of the wall. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.6)
			COMMENTS:
			WALL THICKNESS: Thickness of bearing walls shall not be less than 1/25 the unsupported height or length, whichever is shorter, nor less than 4 inches. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.7)
			COMMENTS:
С	NC	N/A	Diaphragms
			DIAPHRAGM CONTINUITY: The diaphragms shall not be composed of split-level floors and shall not have expansion joints. (Tier 2: Sec. 4.5.1.1)
			COMMENTS:
$\boxtimes$			CROSS TIES: There shall be continuous cross ties between diaphragm chords. (Tier 2: Sec. 4.5.1.2)

 $\square$ 

 $\square$ 

 $\boxtimes$ 

#### COMMENTS:

PLAN IRREGULITIES: There shall be tensile capacity to develop the strength of the<br/>diaphragm at re-entrant corners or other locations of plan irregularities. This statement shall<br/>apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.1.7)

#### **COMMENTS:**

DIAPHRAGM REINFORCEMENT AT OPENINGS: There shall be reinforcing around all diaphragm openings larger than 50 percent of the building width in either major plan dimension. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.1.8)

#### **COMMENTS:**

STRAIGHT SHEATHING: All straight sheathed diaphragms shall have aspet ratios less than 2-to-1 for Life Safety and 1-to-1 for Immediate Occupancy in the direction being considered. (Tier 2: Sec. 4.5.2.1)

#### COMMENTS:

SPANS: All wood diaphragms with spans greater than 24 feet for Life Safety and 12 feet for Immediate Occupancy shall consist of wood structural panels or diagonal sheathing. (Tier 2: Sec. 4.5.2.2)

#### COMMENTS:

UNBLOCKED DIAPHRAGMS: All diagonally sheathed or unblocked wood structural panel diaphragms shall have horizontal spans less than 40 feet for Life Safety and 30 feet for Immediate Occupancy and shall have aspect ratios less than or equal to 4-to-1 for Life Safety and 3-to-1 for Immediate Occupancy. (Tier 2: Sec. 4.5.2.3)

#### **COMMENTS:**

NON-CONCRETE FILLED DIAPHRAGMS: Untopped metal deck diaphragms or metal deck diaphragms with fill other than concrete shall consist of horizontal spans of less than 40 feet and shall have span/depth ratios less than 4-to-1. This Statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.3.1)

#### **COMMENTS:**

OTHER DIAPHRAGMS: The diaphragm shall not consist of a system other than wood, metal deck, concrete, or horizontal bracing. (Tier 2: Sec. 4.5.7.1)

#### **COMMENTS:**

С	NC	N/A	Connections
			UPLIFT AT PILE CAPS: Pile caps shall have top reinforcement and piles shall be anchored to the pile caps for Life Safety, and the pile cap reinforcement and pile anchorage shall be able to develop the tensile capacity of the piles for Immediate Occupancy. (Tier 2: Sec. 4.6.3.10)

**COMMENTS:** 

#### 3.8 Geologic Site Hazards and Foundations Checklist

Geologic Site Hazards and Foundations Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

C	NC	N/A	Geologic Site Hazards
			LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance shall not exist in the foundation soils at depths within 50 feet under the building for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.7.1.1)
			COMMENTS: Could not be verified.
			SLOPE FAILURE: The building site shall be sufficiently remote from potential earthquake- induced slope failures or rockfalls to be unaffected by such failures or shall be capable of accommodating any predicted movements without failure. (Tier 2: Sec. 4.7.1.2)
			COMMENTS:
			SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site is not anticipated. (Tier 2: Sec. 4.7.1.3)
			COMMENTS: Could not be verified.
Ċ	NC	N/A	<b>Condition of Foundations</b>
			FOUNDATION PERFORMANCE: There shall be no evidence of excessive foundation movement such as settlement or heave that would affect the integrity or strength of the structure. (Tier 2: Sec. 4.7.2.1)
			COMMENTS:
			DETERIORATION: There shall not be evidence that foundation elements have deteriorated due to corrosion, sulfate attack, material breakdown, or other reasons in a manner that would affect the integrity or strength of the structure. (Tier 2: Sec. 4.7.2.2)
			COMMENTS: Could not be verified.

	1.4	•	
An	ntrh	riiim	
	areo	TTOTTT	

NC

С

 $\square$ 

N/A

#### **Capacity of Foundations**

POLE FOUNDATIONS: Pole foundations shall have a minimum embedment depth of 4 feet for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.7.3.1)

#### **COMMENTS:**

 $\bigcirc$   $\bigcirc$  OVERTURNING: The ratio of the horizontal dimension of the lateral-force-resisting system at the foundation level to the building height (base/height) shall be greater than 0.6Sa. (Tier 2: Sec. 4.7.3.2)

#### COMMENTS:

TIES BETWEEN FOUNDATION ELEMENTS: The foundation shall have ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Class A, B, or C. (Section 3.5.2.3.1, Tier 2: Sec. 4.7.3.3)

#### **COMMENTS:**

DEEP FOUNDATIONS: Piles and piers shall be capable of transferring the lateral forces between the structure and the soil. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.7.3.4)

#### **COMMENTS:**

SLOPING SITES: The difference in foundation embedment depth from one side of the building to another shall not exceed one story in height. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.7.3.5)

#### **COMMENTS:**

Auditorium

#### 3.9.1 Basic Nonstructural Component Checklist

This Basic Nonstructural Component Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С NC N/A **Partitions**  $\boxtimes$ UNREINFORCED MASONRY: Unreinforced Masonry or hollow clay tile partitions shall be braced at spacing equal to or less than 10 feet in levels of low or moderate seismicity and 6 feet in levels of high seismicity. (Tier 2: Sec. 4.8.1.1) **COMMENTS:** С N/A **NC Ceiling Systems**  $\boxtimes$ SUPPORT: The integrated suspended ceiling system shall not be used to laterally support the tops of gypsum board, masonry, or hollow clay tile partitions. Gypsum board partitions need not be evaluated where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.3.1) **COMMENTS:** С NC N/A **Light Fixtures**  $\boxtimes$ П EMERGENCY LIGHTING: Emergency lighting shall be anchored or braced to prevent falling during an earthquake. (Tier 2: Sec 4.8.3.1) **COMMENTS:** С NC N/A **Cladding and Glazing**  $\boxtimes$ CLADDING ANCHORS: Cladding components weighing more than 10 psf shall be mechanically anchored to the exterior wall framing at a spacing equal to or less than 4 feet. A spacing of up to 6 feet is permitted where only Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.1) **COMMENTS:**  $\boxtimes$ DETERIORATION: There shall be no evidence of deterioration, damage or corrosion in any of the connection elements. (Tier 2: Sec. 4.8.4.2) **COMMENTS:**  $\boxtimes$ CLADDING ISOLATION: For moment frame buildings of steel or concrete, panel connections shall be detailed to accommodate a story drift ratio of 0.02. Panel connection detailing for a story drift ratio of 0.01 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.3) **COMMENTS:** 

Audit	orium		Screening Phase (Tier 1) – Basic Nonstructural Component A14.0170.0
		. 🛛	MULTI-STORY PANELS: For multi-story panels attached at each floor level, panel connections shall be detailed to accommodate a story drift ratio of 0.02. Panel connection detailing for a story drift ratio of 0.01 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.4)
			COMMENTS:
		$\boxtimes$	BEARING CONNECTIONS: Where bearing connections are required, there shall be a minimum of two bearing connections for each wall panel. (Tier 2: Sec. 4.8.4.5)
			COMMENTS
			INSERTS: Where inserts are used in concrete connections, the inserts shall be anchored to reinforcing steel or other positive anchorage. (Tier 2: Sec. 4.8.4.6)
			COMMENTS:
			PANEL CONNECTIONS: Exterior cladding panels shall be anchored out-of-plane with a minimum of 4 connections for each wall panel. Two connections per wall panel are permitted where only the Basic Nonstandard Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.7)
			COMMENTS:
С	NC	N/A	Masonry Veneer
с —		N/A	Masonry Veneer SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)
с 		N/A	Masonry Veneer SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1) COMMENTS:
с —		N/A	Masonry Veneer         SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)         COMMENTS:         TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. The ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for every 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2)
c		N/A	Masonry Veneer         SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)         COMMENTS:         TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. The ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for every 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2)         COMMENTS:
с			Masonry Veneer         SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)         COMMENTS:         TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. The ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for every 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2)         COMMENTS:         WEAKENED PLANES: Masonry veneer shall be anchored to the backup adjacent to weakened planes, such as at the locations of flashing. (Tier 2: Sec. 4.8.5.3)
		N/A	Masonry Veneer         SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)         COMMENTS:         TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. The ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for every 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2)         COMMENTS:         WEAKENED PLANES: Masonry veneer shall be anchored to the backup adjacent to weakened planes, such as at the locations of flashing. (Tier 2: Sec. 4.8.5.3)         COMMENTS:
			Masonry Veneer         SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1)         COMMENTS:         TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. The ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for every 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2)         COMMENTS:         WEAKENED PLANES: Masonry veneer shall be anchored to the backup adjacent to weakened planes, such as at the locations of flashing. (Tier 2: Sec. 4.8.5.3)         COMMENTS:         DETERIORATION: There shall be no evidence of deterioration, damage, or corrosion in any part of the connection elements. (Tier 2: Sec. 4.8.5.4)

Audit	orium		Screening Phase (Tier 1) – Basic Nonstructural Component A14.0170.00			
С	NC	N/A	Parapets, Cornices, Ornamentation, and Appendages			
			URM PARAPETS: There shall be no laterally unsupported unreinforced masonry parapets or cornices with height-to-thickness ratios greater than 1.5. A height to thickness ratio of up to 2.5 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.8.1)			
			COMMENTS:			
			CANOPIES: Canopies located at building exits shall be anchored to the structural framing at a spacing of 6 feet or less. An anchorage spacing of up to 10 feet is permitted where only Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.8.2)			
			COMMENTS:			
С	NC	N/A	Masonry Chimneys			
			URM CHIMNEYS: No unreinforced masonry chimney shall extend above the roof surface more than twice the least dimension of the chimney. A height above the roof surface up to three times the least dimension of the chimney is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.9.1)			
			COMMENTS:			
C	NC	N/A	Stairs			
			URM WALLS: Walls around stair enclosures shall not consist of unbraced hollow clay tile or unreinforced masonry with a height-to-thickness ratio greater than 12-to-1. A height-to-thickness ratio of up to 15-to-1 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.10.1)			
			COMMENTS:			
			STAIR DETAILS: In moment frame structures, the connection between the stairs and the structure shall not rely on shallow anchors in concrete. Alternatively, the stair details shall be capable of accommodating the drift calculated using the Quick Check procedure of Section 3.5.3.1 without including tension in the anchors. (Tier 2: Sec. 4.8.10.2)			
			<b>COMMENTS:</b> In the 1990 expansion area of the main building, which includes the Auditorium area, the stairs do not appear to have slip connections to accommodate building drift			
С	NC	N/A	Building Contents and Furnishing			
			TALL NARROW CONTENTS: Contents over 4 feet in height with a height-to-depth or height-to-width ratio greater than 3-to-1 shall be anchored to the floor slab or adjacent structural walls. A height-to-depth or height-to width ratio of up to 4-to-1 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.11.1)			
			COMMENTS:			
ASCE	31-03		Seismic Evaluation of Existing Buildings			

i

Audit	orium		Screening Phase (Tier 1) – Basic Nonstructural Component	A14.0170.00
C	NC	N/A	Mechanical and Electrical Equipment	
$\boxtimes$			EMERGENCY POWER: Equipment used as part of an emergency power system s mounted to maintain continued operation after an earthquake. (Tier 2: Sec. 4.8.12.)	shall be .1)
			COMMENTS:	
			HAZARDOUS MATERIAL EQUIPMENT: HVAC or other equipment containing shall not have damaged supply lines or unbraced isolation supports. (Tier 2: Sec. 4)	g material 4.8.12.2)
			COMMENTS:	
$\boxtimes$			DETERIORATION: There shall be no evidence of deterioration, damage, or corro of the anchorage or supports of mechanical or electrical equipment. (Tier 2: Sec. 4	sion in any I.8.12.3)
			COMMENTS:	
			ATTACHED EQUIPMENT: Equipment weighing over 20 lb that is attached to ce walls, or other supports 4 feet above the floor level shall be braced. (Tier 2: Sec. 4	ilings, .8.12.4)
			<b>COMMENTS:</b> There appears to be no lateral bracing for the suspended equipment suspended acoustical panels in the auditorium.	nt or the
С	NC	N/A	Piping	
			FIRE SUPPRESSION PIPING: Fire suppression piping shall be anchored and brac accordance NFPA-13 (NFPA, 1996). (Tier 2: Sec. 4.8.13.1)	ced in
			<b>COMMENTS:</b> The fire suppression piping did not appear to have lateral bracing.	
			FLEXIBLE COUPLINGS: Fluid, gas, and fire suppression piping shall have flexib couplings. (Tier 2: Sec. 4.8.13.2)	ble
		·	COMMENTS: Could not be verified.	
С	NC	N/A	Hazardous Materials Storage and Distribution	
			TOXIC SUBSTANCES: Toxic and hazardous substances stored in breakable conta be restrained from falling by latched doors, shelf lips, wires, or other methods. (Ti 4.8.15.1)	ainers shall er 2: Sec.
			COMMENTS:	

#### 3.9.2 Intermediate Nonstructural Component Checklist

Auditorium

This Intermediate Nonstructural Component Checklist shall be completed where required by Table 3-2. The Basic Nonstructural Component Checklist shall be completed prior to completing this Intermediate Nonstructural Component Checklist.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С	NC	N/A	Ceiling Systems
		$\boxtimes$	LAY-IN TILES: Lay-in tiles used in ceiling panels located at exits and corridors shall be secured with clips. (Tier 2: Sec. 4.8.2.2)
			COMMENTS: There are no suspend ceiling systems at exits or corridors
			INTEGRATED CEILINGS: Integrated suspended ceilings at exits and corridors or weighing more than 2 pounds per square foot shall be laterally restrained with a minimum of four diagonal wires or rigid members attached to the structure above at a spacing equal to or less than 12 feet. (Tier 2: Sec. 4.8.2.4)
			<b>COMMENTS:</b> There are no suspend ceiling systems at exits or corridors
			SUSPENDED LATH AND PLASTER: Ceilings consisting of suspended lath and plaster or gypsum board shall be attached to resist seismic forces for every 12 square feet of area. (Tier 2: Sec. 4.8.2.4)
			COMMENTS:
С	NC	N/A	Light Fixtures
	$\boxtimes$		INDEPENDENT SUPPORT: Light fixtures in suspended grid ceilings shall be supported independently of the ceiling suspension system by a minimum of two wires at diagonally
			opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2)
			opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2) <b>COMMENTS:</b> The suspended light fixtures in the auditorium appear to not be laterally braced.
С	NC	N/A	COMMENTS: The suspended light fixtures in the auditorium appear to not be laterally braced. Cladding and Glazing

Audit	orium		Screening Phase (Tier 1) – Intermediate Nonstructural Component A14.0170.00
С	NC	N/A	Parapets, Cornices, Ornamentation, and Appendages
			CONCRETE PARAPETS: Concrete parapets with height-to-thickness ratios greater than 2.5 shall have vertical reinforcement. (Tier 2: Sec. 4.8.8.3)
			COMMENTS
			APPENDAGES: Cornices, parapets, signs, and other appendages that extend above the highest point of anchorage to the structure or cantilever from exterior wall faces and other exterior wall ornamentation shall be reinforced and anchored to the structural system at a spacing equal to or less than 10 feet for Life Safety and 6 feet for Immediate Occupancy. This requirement need not apply to parapets or cornices compliant with Section 4.8.8.1 or 4.8.8.3. (Tier 2: Sec. 4.8.8.4)
			COMMENTS:
С	NC	N/A	Masonry Chimneys
			ANCHORAGE: Masonry chimneys shall be anchored at each floor level and the roof. (Tier 2: Sec. 4.8.9.2)
			COMMENTS:
С	NC	N/A	Mechanical and Electrical Equipment
			VIBRATION ISOLATORS: Equipment mounted on vibration isolators shall be equipped with restraint or snubbers. (Tier 2: Sec. 4.8.12.5)
			COMMENTS:
С	NC	N/A	Ducts
			STAIR AND SMOKE DUCTS: Stair pressurization and smoke control ducts shall be braced and shall have flexible connections at seismic joints. (Tier 2: Sec. 4.8.14.1)
		١	COMMENTS:

# Supporting Calculations

## Roof Loads (psf)

	Flr. Mass
Membrane Roof	5
Steel Framing	10
Suspended Ceiling/Acoustical	3
Mechanical and Electrical	3
Fire Sprinklers	. 1
Exterior Walls	61
Egress Opening Headers	5
Column (TS 7x7x1/4)	1
Miscellaneous	1
Dead Load	90
Live Load	20

## Floor Loads (psf)

1

\*\*Slab on grade

Total Roof SF = 4,778 sf

Total Building Weight, Dead Load =  $\begin{array}{c} 430 \\ 0 \end{array}$  kips Live Load=  $\begin{array}{c} 0 \\ 0 \end{array}$  kips  $\Sigma = \begin{array}{c} 430 \\ kips \end{array}$ 

## Building Period (T)

$T = (C_t)(h_n)^{\beta}$	
C <sub>t</sub> =	0.020 (For all other framing systems)
hn =	20 ft
β =	0.75 (For all other framing systems)
Τ=	0.189 seconds

## Story Shear Forces (V)

## V=CS<sub>a</sub>W

C =	1	(From ASCE 31 Table 3-4)
W =	430	kips (From mass take off calculations spreadsheets)
S <sub>D1</sub> = S <sub>a</sub> =S <sub>D1</sub> /T	0.391 2.067	g
S <sub>a</sub> shall no	ot exceed S <sub>D</sub>	s Therefore:
S <sub>DS</sub> =	0.626	ខ្ល

	therefor:
S <sub>a</sub> =	<b>0.626</b> g

Seismic Shear:

V =	0.626 *W	kips
<b>V</b> =	269	kips

Auditorium

## Shear Wall Area for Shear Stress in Concrete Shear Walls Quick Calc (3.5.3.3):

All Directions of Loading					
Location Length, ft Area, sf					
Roof Level					
8" Wall	123	82			
	Σ=	82			

## Shear Stress in Concrete Shear Walls (3.5.3.3):

Determined as follows:

$$vj^{avg} = \frac{1}{m} \left( \frac{V_j}{A_w} \right)$$

m = Component modification factor: Taken from table 3-7 Vj = story shear Aw = Sum of horizontal cross-section areas of walls

Limit shear stress to greater of:

100psi or 2√f'c

$$2\sqrt{f'c} = 2 \times \sqrt{3000 \ psi} = 109 \ .5 \ psi$$

0.1095 ksi CONTROLS 109.5 psi CONTROLS or **All Directions** vi<sup>avg</sup> (ksi) V<sub>i</sub> (kips) DCR Less than?  $A_w$  (in<sup>2</sup>min) Story m **Roof Level** 11760 269 4.0 0.01 0.1 OKAY

( ;	Designer_CMG BergerABAM Bubject Auditorium Designer_CMG Date 12-2013										
	Determine Wall WT to ROOF-										
	TRIB = 8.75 F4 $R = 39 F4$ : $L = 2\pi r^{2} = 245 F4$										
	18" reinforced concrete walls 8"(8,75,f4)= 6 sf (150 pcf) - 900 plf										
	Total $W_T = \frac{900 \text{ pif}}{245 \text{ f}} + 80 \text{ f}}$ = 292,500 #										

Total Area = 
$$\pi r^2 = 4,778$$
 sf.  
 $PSF = 292,500 \# / 4,778$  sf. = [61 psf.]

Auditorium SiF. =  

$$\pi R^2 = \pi (39 \text{ ff})^2 = 4,778 \text{ sf.}$$
  
Column WF =  $7 \times 7 \times 1/4 = 23 \text{ plf}$   
Total WT / SF =  $23 \text{ plf}(4)(9 \text{ ff}) / 4,778 = \sqrt{1795}$ 

$$\frac{D_{oor} Headers -}{2 \times [14 ft(3ft \times 1ft)]} = 84 cf. (150 pcf! = 12,000 # (2)) = 25,200 # (4,778 sf.) = 5 psf.$$

. )

Proper Salesn (ibrary  
Street ATU(0) (20.00)  
Designer ATU(0) (20.00)  
Designer ATU(0) (20.00)  
Designer ATU(0) (20.00)  
Designer CMG  
Designer CMG  
Now I2 (203)  
Shear stress check ~  
\* stree auditorium is circular, treat length of  
Shear wall to resist shear forces as you  
would in a pipe.  
  

$$M = \frac{1}{2}(2\pi r) = \pi r$$
  
 $mp$  this situation is worst case scenario  
 $\frac{1}{2} \cdot L_{gr wall} = \pi r = \pi (39.44) = 1/22.5 \text{ ft}$   
  
Reinforcing concreter  
Steel:  $\pm 50$  15" o.c. = 0.31 in<sup>2</sup>  
concrete:  $15" \times 8" = 120 \text{ in}^2$   
ratio = 0.002.58 > 0.0015  $\cdot 0K$   
(H) Steel:  $\pm 40$  12" o.c. = 0.2 in<sup>2</sup>  
concrete:  $12'' \times 8" = 96 \text{ in}^2$   
Vatio > 6.002.08  $\perp 0.002.5$   $\cdot 0.54$ 

•

(

. )

.

 $\left( \begin{array}{c} c \end{array} \right)$ 

()

TABLE 3-CARBON STEEL KWIK BOLT-II ALLOWABLE TENSION AND SHEAR VALUE	S (in pounds), NORMAL-WEIGHT CONCRETE
---	---------------------------------------

	L' = 2.000 ps					'_ = 3,000 psl			L' = 4,000 pei				
		Tention			Tension			Teasion			Tension		
ANCHOR. DIAMETER	ANCHOR DEPTH	With So, jast.	Without Sa. inch.	Sheer	With Sp. josp.	Without Sp. insp.	Shear	With Sp. insp.	Without Sp. Insp.	Sheer	With Sp. Inop.	Without Sp. Insp.	Streer
1/4	1 <sup>1</sup> /s <sup>3</sup>	245	120	400	300	150	400	.350	175	400	430	215	400
	2	525	265	400	550	280	400	590	295	400	625	.315	400
	33/4	625	315	400	625	315	400	625	315	400	625	· 315	400
3 <sub>/8</sub>	15/83	500	250	925	605	300	975	710	355	1,025	800	400	1,025
	21/2	1.125	565	1,100	1,210	605	1,100	1,290	645 ·	1,100	1,450	725	1,100
	41/4	1,190	595	1,100	1,235	615	1,100	1,285	640	1,100	1,450	725	1,100
	21/43	860	430	1,810	960	480	1,840	1,065	530	1,840	1,625	815	1,840
· 1/2	31/2	1.750	875	1,840	2,000	1,000	1,840	2,250	1,125	1,840	2,625	1,315	1,840
12	6	1.950	975	1,840	2,165	1,080	1,840	2,375	1,190	1,840	2,625	1,315	1,840'
• ·· · ·	2 <sup>3</sup> /4 <sup>3</sup>	1,425	710	2,875	1,685	845	2,875	1,950	975	2,875	2,500	1,250	2,875
<sup>5</sup> /8	4	2,180	1,125	3,125	2,670 (	1,335	3,125	3,090	1,545	3,125	3,925	1,965	3,125
	7	3,000	1,500	3,125	3,250	1,625	3,125	3,500	1,750	3,125	3,925	1,965	3,125
3/4	31/43	1,850	925	3,875	2,175	1,090	3,875	2,500	1,250	3,875	3,000	1,500	3,875
	43/4	2,750	1,375	4,225	3,625	1,940	4,225	4,500	2,250	4,225	5,060	2,530	4,225
	8	3,750	1,875	4,225	4,625	2,315	4,225	5,500	2,750	4,225	5,925	2,965	4,225
_ 1	41/23	2,930	1,465	6,625	3,650	1,825	7,125	4,375 .	2,190	7,625	4,360	2,180	8,625
	6	3,990	1,995	8,625	5,310	2,655	8,625	6,625	3,315	8,625	7,875	3,940	8,625
	9	6,040	3,020	8,625	7,050	3,525	8,625	8,055	4,025	8,625	10,000	5,000	8,625

For SI: 1 inch = 25.4 mm, 1 psi = 6.9 kPa, 1 lb. = 4.45 N.

<sup>1</sup>See Table 2 footnotes.

17

<sup>2</sup>Allowable loads may be increased by 33<sup>1</sup>/<sub>3</sub> percent for short-term loading due to wind or seismic forces.

<sup>3</sup>Only the long-threaded style KB-II anchor installed at this embedment depth is permitted to be used to resist shear due to wind or seismic forces. Long threaded style KB-II anchors have a thread length greater than three bolt diameters.

TABLE 4-STAINLESS STEEL KWIK BOLT-II ALLOWABLE TENSION AND SHEAR VALUES (in pounds), NORMAL-WEIGHT CONCRETE<sup>1,2</sup>

		f_' = 2,000 pei.			fe' = 3,000 psi				£' = 4,000 psi		f <sub>a</sub> ' = 8,908 pst		
		Tension		T	Tension			Tension			Tension		1
ANCHOR	ANCHOR DEPTH (inches)	With Sp. imep.	Without Sp. Insp.	Shew	With Sp. Insp.	Without Sp. Insp	Shear	With Sp. Jasp.	Wilhout Sp. Insp.	Sheer	With Sp. insp.	Withowi Sp. imsp.	Shear
- teroni	11/83	170	85	525	230	115	540	245	120	550	350	175	550
1/4	2	425	210	550	500	250	550	500	250	550	520	260	550
	33/4	520	260	550	520	260	550	520	260	550	520	260	550
	15/83	400	200	825	460	230	950	515	260	1,075	625	315	1,150
<sup>3</sup> /8	21/2	875	440	1,250	1,025	515	1,250	1,175	590	.1,250	1,350	675	1,250
	41/4	1.000	500	1,250	1,145	625	1,250	1,350	675	1,250	1,350	675	1,250
1/0	21/43	800	400	1.700	1,000	500	1,740	1,200	600	1,775	1,250	625	2,085
	31/2	1.250	625	2,085	1,625	815	2,085	2,000	1,000	2,085	2,250	1,125	2,085
12	6	1.375	690	2,085	1,765	880	2,085	2,150	1,075	2,085	2,550	1,275	2,085
<sup>5</sup> /8	73/43	1.020	510	2.625	1,250	625	2,875	1,475	735	3,125	1,800	900	3,125
	4	1.730	865	3.125	2,220	1,110	3,125	2,715	1,355	3,125	3,000	1,500	3,125
	7	2,250	1.125	3.125	2.825	1,415	3,125	3,425	1,715	3,125	3,425	1,715	3,125
3/4	31/,3	1.450	725	2,700	1.825	915	3,100	2,200	1,100	3,500	2,450	1,225	4,500
	43/4	2,350	1.175	4.225	2,990	1,495	4,365	3,625	1,815	4,500	4,375	2,190	4,500
	8	2 750	1.375	4.500	3.500	1.815	4,500	4,250	2,125	4,500	4,800	2,400	4,500
1	A1/a3	2 300	1 1 50	5,700	2.850	1.425	6,350	3,400	1,700	7,000	4,500	2,250	7,000
		3 740	1 870	7 000	4.930	2.465	7.000	6,120	3,060	7,000	6,875	3,440	7,000
		5 250	2 625	7,000	7.075	3.540	7.000	8,800	4,400	7,000	8,800	4,400	7,000
	1 2	السمرد ا	1 4,020	.,	1 .,010				. <u></u>				

For SI: 1 inch = 25.4 mm, 1 psi = 6.9 kPa, 1 lb. = 4.45 N.

<sup>1</sup>See Table 2 footnotes.

<sup>2</sup>Allowable loads may be increased by 33<sup>1</sup>/<sub>3</sub> percent for short-term loading due to wind or seismic forces.

<sup>3</sup>Anchors installed at this embedment depth shall not be used to resist shear due to wind or seismic forces.

#### Salem Central Public Library ASCE 31-03 Seismic Evaluation Checklists: PARKING GARAGE

- 3.7.9 Basic Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragms
- 3.7.9S Supplemental Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragms
- 3.8 Geologic Site Hazards and Foundations Checklist
- 3.9.1 Basic Nonstructural Component Checklist
- 3.9.2 Intermediate Nonstructural Component Checklist
Screening Phase (Tier 1)

#### 3.7.9 Basic Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragms

This Basic Structural Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier I Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

U	NC	N/A	Building System
			LOAD PATH: The structure shall contain a minimum of one complete load path for Life Safety and Immediate Occupancy for seismic force effects from any horizontal direction that serves to transfer the inertial forces from the mass to the foundation. (Tier 2: Sec. 4.3.1.1)
			COMMENTS:
			MEZZANINES: Interior mezzanine levels shall be braced independently from the main structure, or shall be anchored to the lateral-force-resisting elements of the main structure. (Tier 2: Sec. 4.3.1.3)
			COMMENTS:
, 🗖			WEAK STORY: The strength of the lateral-force-resisting system in any story shall not be less than 80 percent of the strength in an adjacent story, above or below, for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.1)
·			<b>COMMENTS:</b> The strength of the lateral-force-resisting system supporting the Upper Level is 49% less than the strength of the lateral-force resisting system supporting the Middle Level.
			SOFT STORY: The stiffness of the lateral-force-resisting system in any story shall not be less than 70 percent of the lateral-force-resisting system stiffness in an adjacent story above or below, or less than 80 percent of the average lateral-force-resisting system stiffness of the three stories above or below for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.2)
		•	<b>COMMENTS:</b> In both the N-S and the E-W directions, the upper story is less than 70% of the lateral-force-resisting system stiffness in the middle story.
			GEOMETRY: There shall be no changes in horizontal dimension of the lateral-force- resisting system of more than 30 percent in a story relative to adjacent stories for Life Safety and Immediate Occupancy, excluding one-story penthouses and mezzanines. (Tier 2: Sec. 4.3.2.3)
	·		COMMENTS:
$\boxtimes$			VERTICAL DISCONTINUITIES: All vertical elements in the lateral-force-resisting system shall be continuous to the foundation. (Tier 2: Sec. 4.3.2.4)

#### COMMENTS:

MASS: There shall be no change in effective mass more than 50 percent from one story to the next for Life Safety and Immediate Occupancy. Light roofs, penthouses, and mezzanines need not be considered. (Tier 2: Sec. 4.3.2.5)

#### **COMMENTS:**

TORSION: The estimated distance between the story center of mass and the story center of rigidity shall be less than 20 percent of the building width in either plan dimension for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.3.2.6)

**COMMENTS:** The distance between the story center of mass and the story center of rigidity is greater than the recommended 20%. There could be substantial rotation of the diaphragm which would lead to increased demands in the columns which were not designed to be part of the lateral-force-resisting system.

DETERIORATION OF CONCRETE: There shall be no visible deterioration of concrete or reinforcing steel in any of the vertical- or lateral-force-resisting elements. (Tier 2: Sec. 4.3.3.4)

**COMMENTS:** There is some minor cracking of the concrete on all areas of the building and around a few connections of the pre-cast panels. The concrete is also deteriorating around some of the double-tee joist connections to exterior beams.

□ □ ⊠ POST-TENSIONING ANCHORS: There shall be no evidence of corrosion or spalling in the vicinity of post-tensioning or end fittings. Coil anchors shall not have been used. (Tier 2: Sec. 4.3.3.5)

#### **COMMENTS:**

CONCRETE WALL CRACKS: All Existing diagonal cracks in wall elements shall be less than 1/8 inch for Life Safety and 1/16 inch for Immediate Occupancy, shall not be concentrated in one location, and shall not form an X pattern. (Tier 2: Sec. 4.3.3.9)

#### **COMMENTS:**

С	NC	N/A	Lateral-Force-Resisting System	
			OMPLETE FRAMES: Steel or concrete frames classified as secondary components shall orm a complete vertical-load-carrying system. (Tier 2: Sec. 4.4.1.6.1)	
			COMMENTS:	
			REDUNDANCY: The number of lines of moment frames in each principal direction shall be greater than or equal to 2 for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.1.1)	

#### **COMMENTS:**

 $\boxtimes$ 

 $\boxtimes$ 

 $\boxtimes$ 

 $\boxtimes$ 

A14.0170.00

SHEAR STRESS CHECK: The shear stress in the concrete shear walls, calculated using the Quick Check procedure of Section 3.5.3.3, shall be less than the greater of 100 psi or  $2\sqrt{f^2}$  for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.1)

**COMMENTS:** The demand-to-capacity ratio is greater than 1.0 (Range is 1.0-2.21) for all levels of the parking garage in the N-S direction of loading except for the very top level which has a demand-to-capacity ratio equal to 1.0.

REINFORCING STEEL: The ratio of reinforcing steel area to gross concrete area shall be not less than 0.0015 in the vertical direction and 0.0025 in the horizontal direction for Life Safety and Immediate Occupancy. The spacing of reinforcing steel shall be equal to or less than 18 inches for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.2

**COMMENTS:** Based on original construction drawings.

C NC N/A

 $\Box$ 

TRANSFER TO SHEAR WALLS: Diaphragms shall be connected for transfer of loads to the shear walls for Life Safety and the connections shall be able to develop the lesser of the shear strength of the walls or diaphragms for Immediate Occupancy. (Tier 2: Sec. 4.6.2.1)

Connections

COMMENTS:

FOUNDATION DOWELS: Wall reinforcement shall be doweled into the foundation for Life Safety, and the dowels shall be able to develop the lesser of the strength of the walls or the uplift capacity of the foundation for Immediate Occupancy. (Tier 2: Sec. 4.6.3.5)

COMMENTS:

#### 3.7.98 Supp. Structural Checklist for Building Type C2: Concrete Shear Walls with Stiff Diaphragm

This Supplemental Structural Checklist shall be completed where required by Table 3-2. The Basic Structural Checklist shall be completed prior to completing this Supplemental Structural Checklist.

С	NC	N/A	Lateral-Force-Resisting System
			DEFLECTION COMPATIBILITY: Secondary components shall have the shear capacity to develop the flexural strength of the components for Life Safety and shall meet the requirements of Sections 4.4.1.5.9, 4.4.1.4.10, 4.4.1.4.11, 4.4.1.4.12 and 4.4.1.4.15 for Immediate Occupancy (Tier 2: Sec. 4.4.1.6.2)
			<b>COMMENTS:</b> The 18" x 18" reinforced columns do not have enough horizontal reinforcement to resist the shear demand when the maximum moment, Mpr is applied. The shear demand is roughly 61 kips and the capacity is 29 kips.
			FLAT SLABS: Flat slabs/plates not part of the lateral-force-resisting system shall have continuous bottom steel through the column joints for Life Safety and Immediate Occupancy. (Tier 2: 4.4.1.6.3)
			COMMENTS:
			COUPLING BEAMS: The stirrups in coupling beams over means of egress shall be spaced at or less than $d/2$ and shall be anchored into the confined core of the beam with hooks of 135° or more for Life Safety. All coupling beams shall comply with the requirements above and shall have the capacity in shear to develop the uplift capacity of the adjacent wall for Immediate Occupancy. (Tier 2: Sec. 4.4.2.2.3)
			COMMENTS:
			OVERTURNING: All shear walls shall have aspect ratios less than 4-to-1. Wall piers need not be considered. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.4)
			COMMENTS:
			CONFINEMENT REINFORCING: For shear walls with aspect ratios greater than 2-to-1, the boundary elements shall be confined with spirals or ties with spacing less than $8d_b$ . This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.5)
			COMMENTS:
		$\boxtimes$	REINFORCING AT OPENININGS: There shall be added trim reinforcement around all wall openings with a dimension greater than three times the thickness of the wall. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.6)
			COMMENTS:
			WALL THICKNESS: Thickness of bearing walls shall not be less than 1/25 the unsupported height or length, whichever is shorter, nor less than 4 inches. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.4.2.2.7)

1

#### COMMENTS:

С	NC	N/A	Diaphragms	
			DIAPHRAGM CONTINUITY: The diaphragms shall not be composed of split-level floors and shall not have expansion joints. (Tier 2: Sec. 4.5.1.1)	
			COMMENTS:	
		$\boxtimes$	OPENINGS AT SHEAR WALLS: Diaphragm openings immediately adjacent to the shear walls shall be less than 25 percent of the wall length for Life Safety and 15 percent of the wall length for Immediate Occupancy. (Tier 2: Sec. 4.5.1.4)	
			COMMENTS:	
		$\boxtimes$	PLAN IRREGULITIES: There shall be tensile capacity to develop the strength of the diaphragm at re-entrant corners or other locations of plan irregularities. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.1.7)	
			COMMENTS:	
			DIAPHRAGM REINFORCEMENT AT OPENINGS: There shall be reinforcing around all diaphragm openings larger than 50 percent of the building width in either major plan dimension. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.5.1.7)	
			COMMENTS:	
С	NC	N/A	Connections	
			UPLIFT AT PILE CAPS: Pile caps shall have top reinforcement and piles shall be anchored to the pile caps for Life Safety, and the pile cap reinforcement and pile anchorage shall be able to develop the tensile capacity of the piles for Immediate Occupancy. (Tier 2: Sec. 4.6.3.10)	

#### COMMENTS:

#### 3.8 Geologic Site Hazards and Foundations Checklist

Geologic Site Hazards and Foundations Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

С	NC	N/A	Geologic Site Hazards
			LIQUEFACTION: Liquefaction-susceptible, saturated, loose granular soils that could jeopardize the building's seismic performance shall not exist in the foundation soils at depths within 50 feet under the building for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.7.1.1)
			COMMENTS: Could not be verified.
			SLOPE FAILURE: The building site shall be sufficiently remote from potential earthquake- induced slope failures or rockfalls to be unaffected by such failures or shall be capable of accommodating any predicted movements without failure. (Tier 2: Sec. 4.7.1.2)
			COMMENTS:
			SURFACE FAULT RUPTURE: Surface fault rupture and surface displacement at the building site is not anticipated. (Tier 2: Sec. 4.7.1.3)
			COMMENTS: Could not be verified.
С	NC	N/A	<b>Condition of Foundations</b>
			FOUNDATION PERFORMANCE: There shall be no evidence of excessive foundation movement such as settlement or heave that would affect the integrity or strength of the structure. (Tier 2: Sec. 4.7.2.1)
			COMMENTS:
			DETERIORATION: There shall not be evidence that foundation elements have deteriorated due to corrosion, sulfate attack, material breakdown, or other reasons in a manner that would

**COMMENTS:** Could not be verified.

affect the integrity or strength of the structure. (Tier 2: Sec. 4.7.2.2)

C	NC	N/A	Capacity of Foundations
			POLE FOUNDATIONS: Pole foundations shall have a minimum embedment depth of 4 feet for Life Safety and Immediate Occupancy. (Tier 2: Sec. 4.7.3.1)
			COMMENTS:
			OVERTURNING: The ratio of the horizontal dimension of the lateral-force-resisting system at the foundation level to the building height (base/height) shall be greater than $0.6S_a$ . (Tier 2: Sec. 4.7.3.2)
			COMMENTS:
		-	TIES BETWEEN FOUNDATION ELEMENTS: The foundation shall have ties adequate to resist seismic forces where footings, piles, and piers are not restrained by beams, slabs, or soils classified as Class A, B, or C. (Section 3.5.2.3.1, Tier 2: Sec. 4.7.3.3)
			COMMENTS:
			DEEP FOUNDATIONS: Piles and piers shall be capable of transferring the lateral forces between the structure and the soil. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.7.3.4)
			COMMENTS:
			SLOPING SITES: The difference in foundation embedment depth from one side of the building to another shall not exceed one story in height. This statement shall apply to the Immediate Occupancy Performance Level only. (Tier 2: Sec. 4.7.3.5)
			COMMENTS:

#### 3.9.1 Basic Nonstructural Component Checklist

This Basic Nonstructural Component Checklist shall be completed where required by Table 3-2.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

	С	NC	N/A	Partitions	
				UNREINFORCED MASONRY: Unreinforced Masonry or hollow clay tile partitions shall be braced at spacing equal to or less than 10 feet in levels of low or moderate seismicity and 6 feet in levels of high seismicity. (Tier 2: Sec. 4.8.1.1)	
				COMMENTS:	
	С	NC	N/A	Ceiling Systems	
•				SUPPORT: The integrated suspended ceiling system shall not be used to laterally support the tops of gypsum board, masonry, or hollow clay tile partitions. Gypsum board partitions need not be evaluated where only the Basic Nonstructural Component Checklist is required by	
		•		Table 3-2. (Tier 2: Sec. 4.8.3.1)	
				COMMENTS:	
	С	NC	N/A	Light Fixtures	
•			$\boxtimes$	EMERGENCY LIGHTING: Emergency lighting shall be anchored or braced to prevent falling during an earthquake. (Tier 2: Sec 4.8.3.1)	
				COMMENTS:	
	C	NC	N/A	Cladding and Glazing	
-				CLADDING ANCHORS: Cladding components weighing more than 10 psf shall be mechanically anchored to the exterior wall framing at a spacing equal to or less than 4 feet. A spacing of up to 6 feet is permitted where only Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.1)	
				<b>COMMENTS:</b> The pre-cast concrete panels used on the exterior of the parking garage are anchored at each end, or at approximately a 24'-0" spacing.	
		$\boxtimes$		DETERIORATION: There shall be no evidence of deterioration, damage or corrosion in any of the connection elements. (Tier 2: Sec. 4.8.4.2)	
				<b>COMMENTS:</b> There was corrosion on many connecting elements. A few connections appeared to be damaged.	

Parking Garage Screening Phase (Tier 1) - Basic Nonstructural Component A14.0170.00  $\square$  $\boxtimes$ CLADDING ISOLATION: For moment frame buildings of steel or concrete, panel connections shall be detailed to accommodate a story drift ratio of 0.02. Panel connection detailing for a story drift ratio of 0.01 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.3) COMMENTS: The connections of the precast concrete panel cladding to exterior columns do not have slotted connections.  $\Box$  $\boxtimes$ П MULTI-STORY PANELS: For multi-story panels attached at each floor level, panel connections shall be detailed to accommodate a story drift ratio of 0.02. Panel connection detailing for a story drift ratio of 0.01 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.4) COMMENTS: The connections of the precast concrete panel cladding to exterior columns do not have slotted connections. BEARING CONNECTIONS: Where bearing connections are required, there shall be a  $\boxtimes$ minimum of two bearing connections for each wall panel. (Tier 2: Sec. 4.8.4.5) **COMMENTS**  $\boxtimes$ INSERTS: Where inserts are used in concrete connections, the inserts shall be anchored to reinforcing steel or other positive anchorage. (Tier 2: Sec. 4.8.4.6) **COMMENTS:**  $\square$  $\boxtimes$  $\Box$ PANEL CONNECTIONS: Exterior cladding panels shall be anchored out-of-plane with a minimum of 4 connections for each wall panel. Two connections per wall panel are permitted where only the Basic Nonstandard Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.4.7) COMMENTS: There are only two connections for some of the smaller exterior precast wall panels. С NC N/A **Masonry Veneer**  $\boxtimes$  $\boxtimes$ SHELF ANGLES: Masonry veneer shall be supported by shelf angles or other elements at each floor 30 feet or more above ground for Life Safety and at each floor above the first floor for Immediate Occupancy. (Tier 2: Sec. 4.8.5.1) **COMMENTS:**  $\boxtimes$ TIES: Masonry veneer shall be connected to the back-up with corrosion-resistant ties. The ties shall have a spacing equal to or less than 24 inches with a minimum of one tie for every 2-2/3 square feet. A spacing of up to 36 inches is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.5.2) **COMMENTS:** 

WEAKENED PLANES: Masonry veneer shall be anchored to the backup adjacent to

·

Parking Garage Screening Phase (Tier 1) - Basic Nonstructural Component A14.0170.00 weakened planes, such as at the locations of flashing. (Tier 2: Sec. 4.8.5.3) COMMENTS: DETERIORATION: There shall be no evidence of deterioration, damage, or corrosion in any  $\boxtimes$ part of the connection elements. (Tier 2: Sec. 4.8.5.4) **COMMENTS:** С NC N/A Parapets, Cornices, Ornamentation, and Appendages  $\boxtimes$ URM PARAPETS: There shall be no laterally unsupported unreinforced masonry parapets or cornices with height-to-thickness ratios greater than 1.5. A height to thickness ratio of up to 2.5 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.8.1) **COMMENTS:** П  $\square$  $\square$ CANOPIES: Canopies located at building exits shall be anchored to the structural framing at a spacing of 6 feet or less. An anchorage spacing of up to 10 feet is permitted where only Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.8.2) **COMMENTS:** С NC N/A **Masonry Chimneys**  $\boxtimes$  $\square$ URM CHIMNEYS: No unreinforced masonry chimney shall extend above the roof surface more than twice the least dimension of the chimney. A height above the roof surface up to three times the least dimension of the chimney is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.9.1) **COMMENTS:** С N/A NC Stairs  $\boxtimes$ URM WALLS: Walls around stair enclosures shall not consist of unbraced hollow clay tile or unreinforced masonry with a height-to-thickness ratio greater than 12-to-1. A height-tothickness ratio of up to 15-to-1 is permitted where only the Basic Nonstructural Component Checklist is required by Table 3-2. (Tier 2: Sec. 4.8.10.1) **COMMENTS:**  $\boxtimes$ STAIR DETAILS: In moment frame structures, the connection between the stairs and the structure shall not rely on shallow anchors in concrete. Alternatively, the stair details shall be capable of accommodating the drift calculated using the Quick Check procedure of Section 3.5.3.1 without including tension in the anchors. (Tier 2: Sec. 4.8.10.2) **COMMENTS:** С NC N/A **Building Contents and Furnishing**  $\boxtimes$ TALL NARROW CONTENTS: Contents over 4 feet in height with a height-to-depth or  $\square$ height-to-width ratio greater than 3-to-1 shall be anchored to the floor slab or adjacent

Parking Garage		age	Screening Phase (Tier 1) – Basic Nonstructural Component	A14.0170.00
			structural walls. A height-to-depth or height-to width ratio of up to 4-to-1 is per only the Basic Nonstructural Component Checklist is required by Table 3-2. (Ti 4.8.11.1)	nitted where er 2: Sec.
			<b>COMMENTS:</b> Unbraced shelves are present at the 1 <sup>st</sup> floor in the food storage museum/garage area and the library. Unbrace shelves are also present on the 2 <sup>nd</sup> classrooms and conference room areas.	room, old floor in the
С	NC	N/A	Mechanical and Electrical Equipment	
			EMERGENCY POWER: Equipment used as part of an emergency power system mounted to maintain continued operation after an earthquake. (Tier 2: Sec. 4.8.1	1 shall be 2.1)
			COMMENTS:	
			HAZARDOUS MATERIAL EQUIPMENT: HVAC or other equipment containing shall not have damaged supply lines or unbraced isolation supports. (Tier 2: Sec	ng material . 4.8.12.2)
			COMMENTS: Could not be verified.	
			DETERIORATION: There shall be no evidence of deterioration, damage, or comof the anchorage or supports of mechanical or electrical equipment. (Tier 2: Sec.	rosion in any 4.8.12.3)
			COMMENTS:	
			ATTACHED EQUIPMENT: Equipment weighing over 20 lb that is attached to ceilings, walls, or other supports 4 feet above the floor level shall be braced. (Tier 2: Sec. 4.8.12.4)	
			COMMENTS:	
С	NC	N/A	Piping	. *
			FIRE SUPPRESSION PIPING: Fire suppression piping shall be anchored and br accordance NFPA-13 (NFPA, 1996). (Tier 2: Sec. 4.8.13.1)	aced in
			COMMENTS:	
			FLEXIBLE COUPLINGS: Fluid, gas, and fire suppression piping shall have flex couplings. (Tier 2: Sec. 4.8.13.2)	ible
			<b>COMMENTS:</b> Gas pipe at kitchen island does not appear to have flexible coupli $2^{nd}$ floor and ground floor which could lead to a fracture in an earthquake.	ing between
С	NC	N/A	Hazardous Materials Storage and Distribution	
			TOXIC SUBSTANCES: Toxic and hazardous substances stored in breakable con be restrained from falling by latched doors, shelf lips, wires, or other methods. (74.8.15.1)	tainers shall Fier 2: Sec.
			COMMENTS:	

#### 3.9.2 Intermediate Nonstructural Component Checklist

Parking Garage

This Intermediate Nonstructural Component Checklist shall be completed where required by Table 3-2. The Basic Nonstructural Component Checklist shall be completed prior to completing this Intermediate Nonstructural Component Checklist.

Each of the evaluation statements on this checklist shall be marked Compliant (C), Non-compliant (NC), or Not Applicable (N/A) for a Tier 1 Evaluation. Compliant statements identify issues that are acceptable according to the criteria of this standard, while non-compliant statements identify issues that require further investigation. Certain statements may not apply to the buildings being evaluated. For non-compliant evaluation statements, the design professional may choose to conduct further investigation using the corresponding Tier 2 Evaluation procedure; corresponding section numbers are in parentheses following each evaluation statement.

C	NC	N/A	Ceiling Systems		
		$\boxtimes$	LAY-IN TILES: Lay-in tiles used in ceiling panels located at exits and corridors shall be secured with clips. (Tier 2: Sec. 4.8.2.2)		
			COMMENTS: There are no suspend ceiling systems at exits or corridors		
			INTEGRATED CEILINGS: Integrated suspended ceilings at exits and corridors or weighing more than 2 pounds per square foot shall be laterally restrained with a minimum of four diagonal wires or rigid members attached to the structure above at a spacing equal to or less than 12 feet. (Tier 2: Sec. 4.8.2.4)		
			COMMENTS: There are no suspend ceiling systems at exits or corridors		
			SUSPENDED LATH AND PLASTER: Ceilings consisting of suspended lath and plaster or gypsum board shall be attached to resist seismic forces for every 12 square feet of area. (Tier 2: Sec. 4.8.2.4)		
	•		COMMENTS:		
С	NC	N/A	Light Fixtures		
		$\boxtimes$	INDEPENDENT SUPPORT: Light fixtures in suspended grid ceilings shall be supported independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2)		
			independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2)		
			independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2) COMMENTS:		
С	NC	N/A	independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2) COMMENTS: Cladding and Glazing		
C	NC	N/A	Independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2) COMMENTS: Cladding and Glazing GLAZING: Glazing in curtain walls and individual panes over 16 square feet in area, located up to a height of 10 feet above an exterior walking surface, shall have safety glazing. Such glazing located over 10 feet above exterior walking surface shall be laminated annealed or laminated heat-strengthened safety glass or other glazing system that will remain in the frame when glass is cracked. (Tier 2: Sec. 4.8.4.8)		
C		N/A	Independently of the ceiling suspension system by a minimum of two wires at diagonally opposite corners of the fixtures. (Tier 2: Sec. 4.8.3.2) COMMENTS: Cladding and Glazing GLAZING: Glazing in curtain walls and individual panes over 16 square feet in area, located up to a height of 10 feet above an exterior walking surface, shall have safety glazing. Such glazing located over 10 feet above exterior walking surface shall be laminated annealed or laminated heat-strengthened safety glass or other glazing system that will remain in the frame when glass is cracked. (Tier 2: Sec. 4.8.4.8) COMMENTS:		

Parking Garage		ige	Screening Phase (Tier 1) – Intermediate Nonstructural Component A14.0170.00	
С	NC	N/A	Parapets, Cornices, Ornamentation, and Appendages	
<u> </u>			CONCRETE PARAPETS: Concrete parapets with height-to-thickness ratios greater than 2.5 shall have vertical reinforcement. (Tier 2: Sec. 4.8.8.3)	
			COMMENTS: Unable to verify.	
			APPENDAGES: Cornices, parapets, signs, and other appendages that extend above the highest point of anchorage to the structure or cantilever from exterior wall faces and other exterior wall ornamentation shall be reinforced and anchored to the structural system at a spacing equal to or less than 10 feet for Life Safety and 6 feet for Immediate Occupancy. This requirement need not apply to parapets or cornices compliant with Section 4.8.8.1 or 4.8.8.3. (Tier 2: Sec. 4.8.8.4)	
		• •	COMMENTS:	
С	NC	N/A	Masonry Chimneys	
			ANCHORAGE: Masonry chimneys shall be anchored at each floor level and the roof. (Tier 2: Sec. 4.8.9.2)	
			COMMENTS:	
С	NC	N/A	Mechanical and Electrical Equipment	
			VIBRATION ISOLATORS: Equipment mounted on vibration isolators shall be equipped with restraint or snubbers. (Tier 2: Sec. 4.8.12.5)	
			COMMENTS:	
С	NC	N/A	Ducts	
		$\boxtimes$	STAIR AND SMOKE DUCTS: Stair pressurization and smoke control ducts shall be braced and shall have flexible connections at seismic joints. (Tier 2: Sec. 4.8.14.1)	

#### COMMENTS:

# Supporting Calculations

İ

#### Upper Level Loads (psf) - High Side (South Side of Building)

	Flr. Mass
3" Concrete topping slab	38
28" Double Tee Joists	66
Structural Elements	58
Columns (18' x 18")	5
Miscellaneous	1
Dead Load	168
Live Load	40

### Upper Level Loads (psf) - Low Side (North Side of Building)

	Flr. Mass
3" Concrete topping slab	38
28" Double Tee Joists	66
Structural Elements	64
Columns	4
Miscellaneous	1
Dead Load	173
Live Load	40

#### Middle Level Loads (psf) - High Side (South Side of Building)

	Flr. Mass
3" Concrete topping slab	38
28" Double Tee Joists	66
Structural Elements	62
Columns	6
Miscellaneous	2
Dead Load	174
Live Load	40

#### Middle Level Loads (psf) - Low Side (North Side of Building)

	Flr. Mass
3" Concrete topping slab	38
28" Double Tee Joists	66
Structural Elements	68
Columns	5
Miscellaneous	1
Dead Load	178
Live Load	40

.

#### City of Salem, OR Mass Take Offs - Structural Elements

# Upper Level - High Side (South Side of Building)

Location	plf (U.N.O)	total linear ft (U.N.O.)	Weight, lbs
Exterior Walls			
Pre-Cast Panels	450	422	189,900
Interior Walls	psf	total sf	Weight, lbs
12" Concrete Wall	150	600	90,000
Exterior Walls			
10" Concrete Wall	1,250	110	137,500
Beams			
Center Corbel Beam	1,350	140	189,000
Exterior Beam	900	422	379,800
		Total Floor Weight =	986,200
		Total Floor psf=	58

# Upper Level - Low Side (North Side of Building)

Location	plf (U.N.O)	olf (U.N.O) total linear ft (U.N.O.) Weig	
Exterior Walls			
Pre-Cast Panels	450	390	175,500
Interior Walls	psf	total sf	Weight, lbs
12" Concrete Wall	150	1,100	165,000
Exterior Walls			
10" Concrete Wall	1,250	120	150,000
Beams	•		
Center Corbel Beam	1,350	140	189,000
Exterior Beam	900	390	351,000
		Total Floor Weight =	1,030,500
	•	Total Floor psf=	64

# MIddle Level - High Side (South Side of Building)

Location	plf (U.N.O)	total linear ft (U.N.O.)	Weight, lbs
Exterior Walls			
Pre-Cast Panels	450	422	189,900
Interior Walls	psf	total sf	Weight, lbs
12" Concrete Wall	150	1,000	150,000
Exterior Walls			
10" Concrete Wall	1,375	110	151,250
Beams			
Center Corbel Beam	1,350	140	189,000
Exterior Beam	900	422	379,800
	<u>.</u>	Total Floor Weight =	1,059,950
		Total Floor psf=	6 <mark>2</mark> - 100 and

# Middle Level - Low Side (North Side of Building)

Location	plf (U.N.O)	total linear ft (U.N.O.)	Weight, lbs
Exterior Walls			
Pre-Cast Panels	450	390	175,500
Interior Walls	psf	total sf	Weight, lbs
12" Concrete Wall	150	1,000	150,000
Exterior Walls			
10" Concrete Wall	1,375	170	233,750
Beams			
Center Corbel Beam	1,350	140	189,000
Exterior Beam	Exterior Beam 900		351,000
		Total Floor Weight =	1,099,250
		Total Floor psf=	68

DEAD LOAD						
Location psf total sf Weight, lbs						
Upper Level (High Side)	168	17,000	2,856,000			
Upper Level (Low Side)	173	16,200	2,802,600			
Middle Level (High Side)	174	17,000	2,958,000			
Middle Level (Low Side)	178	16200	2,883,600			

**Σ** = **11,500,200** 

#### LIVE LOAD\*

Location	psf	total sf	Weight, lbs
Upper Level (High Side)	40	17,000	680,000
Upper Level (Low Side)	40	16,200	648,000
Middle Level (High Side)	40	17,000	680,000
Middle Level (Low Side)	40	16200	648,000

\*Per ASCE 31-03 Section 3.5.2.1, floor live load in public garages and open parking structures need not be considered.

Т

#### Building Period (T)

$= (C_t)(h_n)$	β			
	C <sub>t</sub> =	0.020	(For all other frai	ming systems)
	hn =	46.5	ft	
	β =	0.75	(For all other fram	ming systems)
-				
	Т=	0 356	seconds	,

#### Story Shear Forces (V)

# $V=CS_{a}W$ C = 1.2 (From ASCE 31 Table 3-4) W = 11,500 kips $S_{D1} = 0.391 g$ $S_{a} = S_{D1}/T 1.098 g$

#### $S_{\mathsf{a}}$ shall not exceed $S_{\mathsf{DS}}$ Therefore:

S <sub>DS</sub> =	0.626 g
	therefor:
S <sub>a</sub> =	<b>0.626</b> g

#### Seismic Shear:

V =	0.751 *W	kips
<b>V</b> =	8,639	kips

# Shear Wall Area for Shear Stress in Concrete Shear Walls Quick Calc (3.5.3.3):

N-S Direction of	Loading		E-W Direction of	Loading	
Location	Length, ft	Area, sf	Location	Length, ft	Area, sf
Upper Level (High Side)			Upper Level (High Side)		
12" Wall	0	0	12" Wall	92	92
10" Wall	60	50	10" Wall	40	33
	Σ =	50		Σ =	125
Upper Level (Low Side)			Upper Level (Low Side)		
12" Wali	0 .	0	12" Wall	184	184
10" Wall	45	38	10" Wall	40	33
	Σ=	38		Σ=	217
Middle Level (High Side)			Middle Level (High Side)		
12" Wall	0	0	12" Wall	92	92
10" Wall	80	67	10" Wall	132	110
	Σ=	67		Σ=	202
Middle Level (Low Side)			Middle Level (Low Side)		
12" Wall	0	0	12" Wall	92	92
10" Wall	120	100	10" Wall	104	87
·	Σ=	100		Σ =	179

# Story Shear Forces in Concrete Shear Walls (3.5.2.2):

	_	$(w_x h_x)^k$	v
F(X)		$\overline{\sum_{i=1}^{n} (w_i h_i)^k}$	V

		<u>n</u>	
$V_{i}$	=	$\mathbf{Y}$	F.
• )		Ļ	÷x
		$\iota = j$	

Story	h <sub>x</sub>	w <sub>x</sub> (kips)	h <sub>x</sub> w <sub>x</sub> <sup>k</sup>	Cv	Fx (kips)
Upper Level (High Side)	32	2,856	91,392	0.37	3,160
Upper Level (Low Side)	22	2,803	61,666	0.25	2,132
Middle Level (High Side)	22	2,958	65,076	0.26	2,250
Middle Level (Low Side)	11	2,884	31,724	0.13	1,097
		Σ =	249,858	1.00	8,639

## Shear Stress in Concrete Shear Walls (3.5.3.3):

Determined as follows:

$$vj^{avg} = \frac{1}{m} \left( \frac{V_j}{A_w} \right)$$

m = Component modification factor: Taken from table 3-7
 Vj = story shear
 Aw = Sum of horizontal cross-section areas of walls

Limit shear stress to greater of:

100psi or 2vf'c

$$2\sqrt{f'c} = 2 \times \sqrt{3000 \ psi} = 109 \ .5 \ psi$$

109.5 psi CONTROLS or 0.1095 ksi CONTROLS

**N-S** Direction

Story	A <sub>w</sub> (in <sup>2</sup> min)	V <sub>j</sub> (kips)	m	v <sub>j</sub> <sup>avg</sup> (ksi)	DCR	Less than?
Upper Level (High Side)	7,200	3,160	4.0	0.11	1.00	OKAY
Upper Level (Low Side)	5,472	5,292	4.0	0.24	2.21	ΝΟΤ ΟΚΑΥ
Middle Level (High Side)	9,648	7,542	4.0	0.20	1.78	ΝΟΤ ΟΚΑΥ
Middle Level (Low Side)	14,400	8,639	4.0	0.15	1.37	ΝΟΤ ΟΚΑΥ

E-W Direction

Story	A <sub>w</sub> (in <sup>2</sup> min)	V <sub>j</sub> (kips)	m	v <sub>j</sub> <sup>avg</sup> (ksi)	DCR	Less than?
Upper Level (High Side)	18,000	3,160	4.0	0.04	0.40	OKAY
Upper Level (Low Side)	31,248	5,292	4.0	0.04	0.39	ΟΚΑΥ
Middle Level (High Side)	29,088	7,542	4.0	0.06	0.59	ΟΚΑΥ
Middle Level (Low Side)	25,776	8,639	4.0	0.08	0.77	ΟΚΑΥ

Project	Salem	Library



Subject Parking Garage

Sheet of						
Job Number						
Designer CMG						
Designer 01010						

Parking Garage

Pre-cast Panels @ Upper & Middle Levels~ 6" thk × 6 ft = 3 sf. (150 pcf) = 450 plf

Double Tee's - 28" → span= 119", 652 pif 260' span Total WT= 60ff (652 p1ff) = 39,120 # Total SF = 60 ft (9.92 ft) = 595 s.f. PSF = 39,120#/595 SF. = [66 psf.]

3" concrete topping~ 1 sf. (3"/12") (150 pcf) = [38 psf]

10" wall~ (10//12/1/) (150 pcf) + 125 psf.] 12" wall - ) 150 psf 7

	Project Salem Library	Sheet of
🕑 BergerABAM	Subject Parking Garage	DesignerCMG
		. Date <u>12-2013</u>
Floors are 10'-8'	"EL Each.	
TRIE	3	
Upper 10 f	4	
Middle II Fa	F.	
Lower H f.	4	
Column Weigh	uts-	
( 18"×18")×	(150  pcf) = 340  plf.	
Upper Level (	High Side) ~	
340 plf (1	10 ++) = 3400 #	
	× 24 columns	
	= 81,600 #/17,000	$s.f. = 4.8 \pi 5 psf$
Upper bevel (1	Low Side)~	
340 plf(1	10 Ft) × 18 columns = 1	61,200 #/16,200 st = 4/PS
All other levels	(High Side)~	
340 016/115	+) x 24 columns = 89,760	)#/17,000 sf = 5.3 psf
All other leve	Is (Low Side)-	#1. 07 27 242 PSF

.

N N N	🕑 BergerABAM	Project Salen Library Subject Parking Garage	Sheet of Job NumberA1U.0170.00 DesignerAU.0170.00 DateIZ-2013
-	Check For Sc	ft Story~	

N-S pirection

$$K_{upper} = R_{F} \left( \frac{10'-8''}{19'} + 4R_{F} \left( \frac{10'-8''}{20'} \right) \right)$$

$$= R_{F} (0.56) + 4R_{F} (0.53) = 5.4 + 4(5.75) = 28.4$$

$$K_{middle} = R_{F} \left( \frac{6'}{19'} \right) + 4\left( \frac{6'}{20'} \right)$$

$$= R_{F} (0.32) + 4\left( (0.30) \right) = 10 + 4(10.78) = 53.12$$

$$\begin{split} \underline{E-W} & \text{Direction} \\ \text{Kupper} = 5 \, \text{R}_{\text{F}} \left( \frac{10'-8''}{16'} \right) \\ &= 5 \, \text{R}_{\text{F}} \left( 0.67 \right) = 5 \left( 4.33 \right) = 2\frac{1.65}{16'} \\ \text{Klower} = \text{R}_{\text{F}} \left( \frac{7}{16'} \right) + 2 \, \text{R}_{\text{F}} \left( \frac{7}{24'} \right) + \text{R}_{\text{F}} \left( \frac{10'-8''}{16'} \right) + \text{R}_{\text{F}} \left( \frac{10'-8''}{24'} \right) \\ &+ \text{R}_{\text{F}} \left( \frac{6'}{6'} \right) + \text{R}_{\text{F}} \left( \frac{6'}{16'} \right) + \text{R}_{\text{F}} \left( \frac{10'}{16'} \right) + 2 \, \text{R}_{\text{F}} \left( \frac{44'}{24'} \right) \\ &+ \text{R}_{\text{F}} \left( \frac{5'-4''}{24'} \right) + \text{R}_{\text{F}} \left( \frac{5'-4''}{16'} \right) \\ &= \text{R}_{\text{F}} \left( 0.44 \right) + 2 \, \text{R}_{\text{F}} \left( 0.29 \right) + \, \text{R}_{\text{F}} \left( 0.67 \right) + \, \text{R}_{\text{F}} \left( 0.44' \right) \\ &+ \text{R}_{\text{F}} \left( 1.0 \right) + 2 \, \text{R}_{\text{F}} \left( 0.38 \right) + 2 \, \text{R}_{\text{F}} \left( 0.17 \right) + \, \text{R}_{\text{F}} \left( 0.22 \right) + \, \text{R}_{\text{F}} \left( 0.33 \right) \\ &= 7.1 + 2 \left( 11.18 \right) + 4.328 + 7.1 + 2.5 + 2 \left( 8.369 \right) \\ &+ 2 \left( 19.42 \right) + 14.9 + 9.747 = 123.6 \end{split}$$

. j

ſ

()

STIFFENES (K)

#### WALL RIGIDITIES 397

TABLE T-1a Coefficients for Deflection and Rigidity of Walls or Piers for Distribution of Horizontal Forces

For use of Table, see Example 4-F

٦

Γ		Fi	xed W	all or P	ier					Cantile	ver W	all or Pi	er		
	∆ <sub>F</sub>	 	Δ	<sub>F</sub> = Defi fixed	ection o	of wall o d botto	or pier m.	 P .		-	$\Delta_C = \underbrace{\mathbb{I}}_{V}$	Deflectio vall or p	n of can ier.	tilever	
			<u>س</u> ۵	$F = \frac{P}{E_m t}$	$\int_{a}^{b} \left[ \left( \frac{h}{d} \right)^{3} \right]$	$+3\left(\frac{h}{d}\right)$		E.			$\Delta_C = -\frac{1}{2}$	$\frac{P}{E_m t} \bigg[ 4 \bigg( \cdot \bigg) \bigg]$	$\left(\frac{h}{d}\right)^3 + 3\left(\frac{h}{d}\right)^3$	$\left(\frac{h}{d}\right)$	
-	4		Δ	F = 0.1	$\left(\frac{h}{d}\right)^3 + 0$	$0.3\left(\frac{h}{d}\right)$		4			∆ <sub>C</sub> = (	$4\left(\frac{h}{d}\right)^3$	$+0.3\left(\frac{1}{2}\right)$	$\left(\frac{h}{l}\right)$	
	$\frac{P}{\Gamma_{\text{manuform}}} = \frac{P}{R_F} = \frac{1}{\Delta_F} \text{ Rigidity of fixed} \qquad											r			
	h = actual height h = 100,000  pounds:  t = 1": F = 1,000,000  psi														
					/ 	P = 100	,000 poi		= 1 ; <i>L</i> <sub>n</sub>	<u></u>			A	0	B
1	h/d	$\Delta_F$	Δc	R <sub>F</sub>	R <sub>c</sub>	h/d	Δ <sub>F</sub>	<u>∆</u> <sub>c</sub>		K <sub>c</sub>	h/a	Δ <sub>F</sub>			
	0.10	0.030	0.030	33.223	32.895	0.45	0.144	0.171	6.939	5.833	0.80	0.291	0.445	3.434	2.248
	0.11	0.033	0.034	30.181	29.822	0.46	0.148	0.177	6.606	5.479	0.82	0.301	0.467	3.321	2.143
	0.12	0.036	0.037	25 497	27.234	0.48	0.155	0.188	6.449	5.312	0.83	0.306	0.478	3.266	2.093
	0.13	0.035	0.043	23.655	23.203	0.49	0.159	0.194	6.299	5.153	0.84	0.311	0.489	3.213	2.045
F	0.15	0.045	0.046	22.057	21.575	0.50	0.163	0.200	6.154	5.000	0.85	0.316	0.501	3.160	1.997
	0.15	0.048	0.050	20.657	20.146	0.51	0.166	0.206	6.014	4.853	0.86	0.322	0.512	3.109	1.952
	0.17	0.051	0.053	19.421	18.880	0.52	0.170	0.212	5.880	4.712	0.87	0.327	0.524	3.011	1.864
	0.18	0.055	0.056	18.321	17.752	0.53	0.1/4	0.219	5.626	4.445	0.89	0.337	0.549	2.963	1.822
	0.19	0.058	0.060	17.335	10.750	0.54	0.170	0.000	5 505	1 310	0.90	0 343	0.562	2.916	1.781
	0.20	0.061	0.063	16.447	15.823	0.55	0.182	0.232	5.389	4.197	0.91	0.348	0.574	2.871	1.741
	0.21	0.064	0.067	12.043	14.233	0.57	0.190	0.245	5.277	4.080	0.92	0.354	0.587	2.826	1.702
	0.22	0.070	0.074	14.242	13.538	0.58	0.194	0.252	5.168	3.968	0.93	0.359	0.601	2.782	1.665
	0.24	0.073	0.078	13.627	12.898	0.59	0.198	0.259	5.062	3.859	0.94	0.365	Q.614	2.739	1.020
	0.25	0.077	0.081	13.061	12.308	0.60	0.202	0.266	4.960	3.754	0.95	0.371	0.628	2.697	1.592
	0.26	0.080	.0.085	12.538	11.760	0.61	0.206	0.274	4.861	3.652	0.96	0.376	0.642	2.000	1.556
	0.27	0.083	0.089	12.053	11.252	0.62	0.210	0.281	4./60	3.555	0.97	0.388	0.670	2.577	1.491
	0.28	0.086	0.093	11.602	10.778	0.63	0.214	0.205	4.583	3.369	0.99	0.394	0.685	2.538	1.460
	0.29	0.089	0.097		10.000	L O CE	0.220	0.305	1 105	3 280	) 1.00	0.400	0.700	2.500	1.429
	0.30	0.093	0.101	10.787	9.921	0.65	0.222	0.305	4.410	3.195	5 1.01	0.406	0.715	2.463	1.398
	0.31	0.096	0.100	10.419	9.165	5 0.67	0.231	0.321	4.328	3.112	2 1.02	0.412	0.730	2.426	1.369
	0.33	0.103	0.113	9.747	8.820	0.68	0.235	0.330	4.247	7 3.032	2 1.03	0.418	0.746	2.391	1.340
	0.34	0.106	0.118	9.440	8.49	5 0.69	0.240	0.338	4.169	2.95	5 1.04	0.424	0.762	2.350	1.312
	0.35	0.109	0.122	2 9.150	8.18	7 0.70	0.244	0.347	4.093	2.88	0 1.05	0.431	0.778	2.321	1.285
	0.36	0.113	0.12	7 8.876	3 7.89	5 0.71	0.249	0.356	6 4.019	2.80	8 1.06 7 1 0 -	0.437	0./94	2.208	1.233
	0.37	0.116	0.13	1 8.610	5 7.61	8 0.72	0.253		3.94	7 2.73 7 2.66	9 1.08	3 0.450	0.828	2.222	1.208
	0.38	0.119	3 0.13 3 0.14	6 8.36 1 8.13	5 7.10	6 0.74	0.250	0.38	4 3.80	9 2.60	1.09	0.45	7 0.845	2.191	1.183
	0.39	0.120				0 0 75	0.05	7 0 30	4 3.71	3 2 54	0 1.1	0 0.46	3 0.862	2 2.159	1.160
	0.40	0.126	5   0.14 n   0.15	5 /.91 1 760	0.80 0 6.64	1 0.75	0.20	2 0.40	4 3.67	8 2.47	78 1.1	1 0.47	0 0.880	2.129	1.136
	0.41	0.13	3 0.15	6 7.49	6 6.42	25 0.7	0.27	7 0.41	4 3.61	5 2.4	18 1.1	2 0.47	6 0.898	3 2.099	1.114
	0.43	3 0.13	7 0.16	7.30	2 6.21	9 0.7	3 0.28	1 0.42	4 3.55	3 2.3	59 1.1	3 0.48	3 0.91		1.092
	0.44	4 0.14	1 0.18	56 7.11	7 6.02	21 0.7	9 0.28	6 0.43	4 3.49	3 2.3	03   1.1	4   0.49	01 0.93	2.040	1.070



$$\frac{N-S \text{ Direction}}{K_{upper} = 28.4}$$

$$K_{middle} = 53.12$$

$$53.12(0.7) = 37.18 > 28.4 \therefore NG.$$

$$\frac{1}{70\%}$$

$$\frac{E-N \text{ Direction}}{K_{upper} = 21.65}$$

$$K_{middle} = 123.6$$

$$123.6(0.7) = 86.52 > 21.65 \therefore NG.$$

Check For Weak Story - compare length of nalls:  
upper level -  
Total length of wall = 16' + 40' + 16' + 24'(7) + 16'  
+ 16'(2) + 20'(2)  
= 328 Ft  
Middle Level = 
$$16'(2) + 40' + 59' + 24'(7) + 16^{3}(2)$$
  
+ 24'(2) + 24'(2) + 16' + 24' + 4' +  
 $16'(2) + 80'$   
=  $16(6 \text{ ft. } (0.8) = 533 > 32.8$   
\* The strength of the upper level  $\therefore N.6.$   
is almost 50% less than the  
strength of the middle level

Eng-001-062209

Eng-001-062209

Product Salem Library  
Product Salem Library  
Deriver Arth.0170.007  
We have Arth.0170.007  
We have Arth.0170.007  
We Arth.0170.007  
Deriver Arth.0170.007  
Deriver Arth.0170.007  
Deriver Arth.0170.007  
Deriver Arth.0170.007  
Deriver Arth.0170.007  
Perform SPEDilumn output, 
$$\phi = 1.0 + 2/c = 3500$$
 psi  
(21.4.5) Mpr = 1.25 Mp = 260 k-ft  
(Derived)  $V = 2mpr = 2(280 k-ft)$   
(Capacity)  $V_S = A_V fyd$   
 $A_V = 2(\#3) = 2(0.11 ms) = 0.22 m^2$   
 $f_Y = (00,000 \text{ psi})(16.1°) = 17.7 k$   
 $\frac{\Phi V_S = 0.221i^2(60,000 \text{ psi})(16.1°) = 17.7 k}{2^n}$   
(Efficient)  $V_C = 2\pi f_S^{-1}$  bud =  $2\pi 3000 \text{ psi}^{-1}(18^n)(14.16 in)$   
 $= -28.78k^{-1}$   
 $F_V = 0.65(28.78k^{-1}) = (8.7k^{-1})$   
Total shear capacity of column  $D + 1/2 = V_C + V_S$   
 $= 10.4k^{-1} + 18.7k^{-2} = 24.1k^{-2} < 52.5k^{-1}$ 

 $\sqrt{2}$ 

STRUCTUREPOINT - spColumn v4.81 (TM) Licensed to: BergerABAM. License ID: 59529-1032107-4-1A81A-1E412 12/16/13 q:\portland\2014\a14.0170\01\engineering\cmg\report documents\seismic evaluation\park...\18x18.col 01:28 PM General Information: \_\_\_\_\_ File Name: q:\portland\2014\a14.0170\01\engineering\cmg\report documents\seismic evalua...\18x18.col Project: Salam Library Engineer: CrviG Column: ACI 318-08 Units: English Code: Slenderness: Not considered Run Option: Investigation Column Type: Structural Run Axis: X-axis Material Properties: = 75 ksi -> 1.25fy (per ACI 21,4,5) = 29000 ksi f'c = 3 ksi Ec = 3122.02 ksi fy Es Ultimate strain = 0.003 in/in Beta1 = 0.85Section: \_\_\_\_\_ Rectangular: Width = 18 in Depth = 18 in Gross section area,  $Ag = 324 \text{ in}^2$  $Ix = 8748 in^{4}$ rx = 5.19615 in  $Iy = 8748 in^{4}$ ry = 5.19615 in  $Y_0 = 0$  in Xo = 0 in Reinforcement:

Bar Set: ASTM A615

S	Siz	ze	Diam (in)	Area	(in^2)	Si	Lze	Diam (in)	Area	(in^2)	S:	ize	Diam	(in)	Area	(in^2)
-																
ŧ	ŧ	3	0.38		0.11	#	4	0.50		0.20	#	5		0.63		0.31
#	ŧ	6	0.75		0.44	#	7	0.88		0.60	#	8		1.00		0.79
#	ŧ	9	1.13		1.00	#	10	1.27		1.27	#	11		1.41		1.56
ŧ	ŧ 1	14	1.69		2.25	#	18	2.26		4.00						

Confinement: Other; #3 ties with #10 bars, #4 with larger bars. phi(a) = 1, phi(b) = 1, phi(c) = 0.65

Layout: Rectangular Pattern: All Sides Equal (Cover to transverse reinforcement) Total steel area: As = 6.32 in^2 at rho = 1.95% Minimum clear spacing = 5.63 in

8 #8 Cover = 1.5 in

Axial Load and Corresponding Moment Capacities:

Load No.	PhiPn kip	PhiMnx k-ft	NA depth in	Dt depth in	eps_t	Phi	
1	-0.0	264.00	4.91	15.63	0.00654	1.000	-
2	25.0	270.07	5.15	15.63	0.00611	1.000	
3	50.0	276.10	5.39	15.63	0.00569	1.000	
4	75.0	282.08	5.65	15.63	0.00529	1.000	
5	100.0	283.26	5.95	15.63	0.00488	0.982	
6	125.0	268.61	6.38	15.63	0.00435	0.905	
7	150.0	-268.61 249.96 -249.96	6.97 6.97	15.63	0.00372	0.815	
		249.90	0.57	-0.00	0.00072	0.010	

\*\*\* End of output \*\*\*

set  $M_n = 280$  k-ft.

2

Page



Confinement: Other

phi(a) = 1, phi(b) = 1, phi(c) = 0.65